



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Santa Fe**
Lease No. **W 079065**
Unit **Magood**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 23, 1961

Well No. **19-G** is located **1950** ft. from **[N]** line and **1130** ft. from **[W]** line of sec. **29**

W-1 Section 29 **T-25N R-19W** **N.M.P.M.**

(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Polish Gallup **San Juan** **New Mexico**

(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **9450** ft. **G.L.**

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

P.B.T.D. - 3274'
Sand-Oil fraced with 15,000# 20/40 sand, 5,000# 10/20 sand, 900 lbs. oil,
flushed with 105 lbs. oil.
Breakdown pr. - 1200#
Maximum - 2500#
Avg. treating pr. - 2500#
I.R. - 30.5 bpm
dropped 14 rubber ball sealers
15 min. shut-in pr. - 1200#
Run 177 lbs., 3270' of 2 1/8" tubing, landed at 3260'
Flowing through tubing.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Astec Oil and Gas Company**

Address **Box # 570**
Farmington, New Mexico

ORIGINAL SIGNED BY JOE C. SALMON
 By **Joe C. Salmon**
 Title **District Superintendent**