

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 070931-3
Unit _____

X			

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 21, 19 60

Glenn H. Callow Gas Unit "A"
Well No. 1 is located 990 ft. from N line and 990 ft. from EX line of sec. 27
N 1/4 Sec. 27 T23N R13W T23N
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Ventura Delta San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)


The elevation of the ~~derrick floor~~ Ground Level above sea level is 9300 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Running and cementing surface casing as follows:

Run 162' of 9 5/8" OD, 40#, 11-80 casing, set at 174'. Cemented w/50 wt. cement, 45 gal, and 125 wt. cement, 25 gal. Cut wire to surface. Plug down 3:45 A.M. 10-18-60. WCT 24 hrs. Pressure tested casing at 500# for 30 min., pressure held O.K.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Tennessee Gas Transmission Company
Address P.O. Box 1714
Durango, Colorado

By [Signature] S. Plumb
Title District Production Superintendent