



RECEIVED
FEB 15 1961

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 101 079065
Unit Reynolds

RECEIVED

FEB 17 1961

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 14, 1961

Well No. 17-4 is located 800 ft. from N line and 2300 ft. from W line of sec. 29
Section 29 T-29N R-13W N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Totah Valley Santa Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5724 ft. 0/1

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

F.B.T.D. - 5968'
Sand-Oil lined with 15,000# 20/40 sand, 3,000# mud, (10/20) and 940 Yals. oil,
flushed with 230 Yals. oil.
Breakdown pr. - 2200#
Maximum - 7750#
Avg. treating pr. - 2600#
I.B. - 28 bpm
5 min. shut-in pr. - 1000#
Run 177 lbs., 3531' of 2 3/8" tubing, landed at 9541'
Perforated nipple - 3504-3509
Flowing through tubing.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Antex Oil and Gas Company

Address Dresser # 370

Farmington, New Mex.

By ORIGINAL SIGNED BY JOE C. SALMON

Joe C. Salmon

Title District Superintendent