

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Santa Fe**
Lease No. **87 - 072063**
Unit **Signal**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 18, 1960

Well No. **7-8** is located **720** ft. from **[N]** line and **390** ft. from **[E]** line of sec. **29**

NE/NE Section 29 (1/4 Sec. and Sec. No.) **T-20N** (Twp.) **R-13W** (Range) **R.M.P.M.** (Meridian)

San Juan (Field) **San Juan** (County or Subdivision) **New Mexico** (State or Territory)

The elevation of the derrick floor above sea level is **5597** ft. **O.L.**

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well was spudded 10/11/60
Set 10 jts., 310' of 5 5/8" surface casing, landed at 321' with 225 sacks cement
Tested casing with 300# pressure for 30 minutes.
No leaks.
Drilled cement plug 10/12/60
Tested casing with 300# pressure for 30 minutes.
No drop in pressure.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Artes Oil and Gas Company**

Address **Box 370**

Farmington, New Mexico

ORIGINAL SIGNED BY JOE C. SALMON
By **Joe C. Salmon**
Title **District Superintendent**