

			0

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office San Juan
Lease No. W - 079063
Unit Rego

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Rego November 7, 1960
Well No. 7-0 is located 710 ft. from N line and 330 ft. from E line of sec. 29
NE 1/4 Sec. 29 T-63N R-13E R.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Total Gallup San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5557 ft. G.L.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total depth - 5500' P.B.T.D. - 5496'
Sand-Oil fraced with 35,000' sand and 732 lbs. oil
Breakdown pressure - 1600'
Fracturing pressure - 3000'
3-min. shut-in - 900'
I.R. - 25 bpm
Perforated nipple - 5158-61
Run 168 jts., 5158' of 2 1/8" tubing, landed at 5358'
Flowing through tubing.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Antec Oil and Gas Company

Address Drews # 370

Pennington, New Mex.

By ORIGINAL SIGNED BY JOE C. SALMON
Joe C. Salmon
Title District Superintendent