						/		
Form 9-331 (May 1963)	DEPART	UNITED STATES SUBMIT IN TRIPLICATE* OEPARTMENT OF THE INTERIOR verse side)				Form approve Budget Bures L LEASE DESIGNATION	10 No. 42-R1424.	
GEOLOGICAL SURVEY					1	14-20-603-2199		
						6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use "APPLICATION FOR PERMIT—" for such proposals.)						Navajo		
I. OIL GAS WELL OTHER						7, UNIT AGREEMENT NAME Northwest Cha Cha		
WELL & WELL OTHER 2. NAME OF OPERATOR						8. FARM OR LEASE NAME		
Humble Oil & Refining Company						NW Cha Cha Unit		
3. ADDRESS OF OPERATOR						9. WELL NO. 24-22		
P. O. Box 120, Denver, Colorado								
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface						Cha Cha Gallup		
SWSW(660' FSL & 1980' FWL) of Section 22						11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA		
					- 1	Sec 22-29N-14W NMPM		
14. PERMIT NO.		15. ELEVATIONS (Show	whether DF, RT	, GR, etc.)	-	12. COUNTY OR PARISH	13. STATE	
		56641 KB				San Juan	New Mexico	
16.	Check A	ppropriate Box To In	dicate Nat	ure of Notice, Report, o	r Oth	ner Data		
•••						ENT REPORT OF:		
TEST WATER S	HUT-OFF	PULL OR ALTER CASING		WATER SHUT-OFF		REPAIRING V	werr	
FRACTURE TREA	1-1	MULTIPLE COMPLETÉ		FRACTURE TREATMENT		ALTERING C.	ASING	
SHOOT OR ACID	IZE	ABANDON*		SHOOTING OR ACIDIZING		ABANDONME	NT. XX	
REPAIR WELL	REPAIR WELL CHANGE PLANS (Other)					11/12		
(Other)	(Other) Completion or Recompl					of multiple completion on Well letion Report and Log form.)		
17. DESCRIBE PROPOSED proposed wor nent to this w	k. If well is direct:	ERATIONS (Clearly state a onally drilled, give subsu	ul pertinent d urface location	etails, and give pertirent da s and measured and true ver	tes, in riical (cluding estimated dat lepths for all marker	e of starting any s and zones perti-	
12-7-71 -	Mix and oum	n 40 sack cemer	nc plug 5	5000-53471 squeez	ed a	t 1900 mx psi	i.	
12-10-71	- Tubing stu	ck at 50001, st	not the	off at 4620', spo	t 15	sack cement	plug	
	2750-2650*	, 15 sack cemer	it plug	950-10501,12 sack	cem	ent plug 0=30)¹ ,	
	squeezed 1	2 sack cement i	in 5½ x 8	3-5/8" annulus.				
12-11-71	- Set regula	tion dry hole m	nark <mark>er ir</mark>	top of casing.		1275	-	
	Intervals	between plugs f	filled w	ith mixad mud.		10	" <i>/</i> //	
2-7-72 -	Location cl	eaned ready for	r inspect	tion.		/ ALUL		
_						FEB 1 5	1972	
cc: 2- NM O&G Commission						OIL CON.	~ / /	
1 - Minerals Supervisor - Navajo Tribe						L'IL CON	COM.	
1 - Midland						DIST.	3	

1 - Clinton



FEB 1 4 1972 U. S. GEOLOGICAL SURVEY

/- °		
18. I hereby certify that the foregoing is true		
SIGNED	Dist. Superintendent	DATE 2-9-72
(This space for Federal or State office use)		
APPROVED BY	THE	DATE