

				X

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Santa Fe**
Lease No. **SP 079065**
Unit **Hagood #1**

SUNDRY NOTICES AND REPORTS ON WELLS

SUNDRIED NOTICE	
NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 24, 1953

Well No. 1 is located 1030 ft. from N line and 790 ft. from E line of sec. 20
SE SE 20 29N 13W N M P M
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
East Autz San Juan New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation of the ~~structure~~ ^{ground} floor above sea level is 5331.7 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

100' - 9 5/8" surface pipe was set with 75 sacks cement.
1107' - 4 1/2" casing was set in 6 3/4" hole on top of Pictured
Cliffs sand at 1107' with Halliburton Packer shoe with
50 sacks cement.
Wagood #1 was temporarily abandoned June 27, 1953 due to tools lost
in hole and unable to fish out or drill around.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Ted W. White
Address 142 Truman U.S.
Albuquerque
New Mexico

By C. E. Stewart
Attn. Acct.
 Title _____