



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Santa Fe**
Lease No. **076958**
Unit **None**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. **11** is located **1450** ft. from **[N]** line and **940** ft. from **[E]** line of sec. **23**
NE 1/4, Section 23 **T-25N** **R-10W** **N.M.P.M.**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Artes Pictured Cliffs **Santa Juan** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **5741** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

Total Depth: 2151'

Sand-Water fraced with 1176 bbls. water and 60,000# sand. Dropped 113 rubber ball sealers.

Breakdown Pressure - 3000#

Breaking Pressure - 1600#

Final Pressure - 470#

I. R. 29.9 bps

Set 86 joints, 2145', of 1" tubing set at 2158'.

END

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Artes Oil & Gas Company**

Address **Box 786, Farmington, New Mexico**

By **ORIGINAL SIGNED BY JOE C. SALMON**
Joe C. Salmon
Title **District Superintendent**