

APPROVED

Form 9-331a
(Feb. 1951)

JUN 22 1956

JERRY W LONG
ACTING DISTRICT ENGINEER

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau 42-R358.3
Approval expires 12-31-55.

Land Office Santa Fe
Lease No. 080723
Unit GALLAGOS CANYON UNIT

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	X
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Farmington, New Mexico May 29, 1956

Well No. 78 is located 1450 ft. from [N] line and 990 ft. from [E] line of sec. 20

NE/4 of Section 20
(1/4 Sec. and Sec. No.)

T-29-N
(Twp.)

R-12-W
(Range)

MGM
(Meridian)

West Kinta-Pictured Cliffs
(Field)

San Juan
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 5621 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On May 18, 1956, this well was spudded. On May 19, 1956, 9-5/8" casing was landed at 101 feet and cemented with 100 sacks cement. After waiting on cement for 24 hours, casing and water shut off were tested with 500 pounds for 30 minutes, with no drop in pressure. Drilling operations were resumed.

On May 22, 1956, 5 1/2" casing was landed at 1637 feet and cemented with 75 sacks cement. After waiting on cement for 4 days, casing and water shut off were tested with two hour balling test. Test proved successful. Completion operations were resumed.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company STANOUND OIL & GAS COMPANY

Address P. O. BOX 487
FARMINGTON, NEW MEXICO

By [Signature]

Title Field Superintendent