## (SUBMIT IN TRIPLICATE)

## UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Budget Bureau No. 42-R358.4. Form Approved.

Senta Pe Land Office

Mare Unit .....

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING.
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	
	155

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

			July 26	19 62×10
Well No. 1940 is locate	d <u>242</u> ft. fro	om. $\mathbb{S}^{\mathbb{N}}$ line a	nd 1045 ft. from	
E. Section 23	T-99A		B.M.P.A.	• •
(1/ Sec. and Sec. No.)	(Twp.)	(Range)	(Meridian)	/ Mexico
(Field)	(Coun	ty or Subdivision)	(5	State or Territory)

The elevation of the derrick floor above sea level is 5753 ft. Golo-

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cement-ing points, and all other important proposed work)

P.B.T.D .- 67301 Band-water fraced with 50,920 gale, water, 47,000% name Breakdown pr. - 17(2) Avg. treating pr.-2400 Max. treating pr.-3300 Avg. I.R .- 37.5 biss dropped of rather ball scalers flushed with 125 Phla. Instant shut in pr.-1100 5 sin. shat in pr.-900 Ran 206 Jts., 6520' of 2 3/8" tubing, landed at 5531' Shut in for gauge.



l underst	and that this plan of work must receive approval in writin	ng by the Geological Survey before operations may be commenced.
Company	Artee Oil & Gas Company	
Address	Crower # 570	
	Parnington, New Maxico	By CRIGINAL SIGNED BY JOE C. SALMOR
	•••••	Title Bistrice Appaintment