Form Approved.
Budget Bureau No. 42-R1424

14-20-603-2199

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

5. LEASE

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Subsurface Safety Valve: Manu. and Type

18. I hereby certify that the foregoing is true and correct

	020200.0.12 00.100	Navajo Tri	ibe
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for slitch pubposeds.)		7. UNIT AGREEMENT NAME NW Cha Cha	
		8. FARM OR LEASE NAME	
1. oil well XX	gas Other	9. WELL NO.	
2. NAME OF OPERATOR		42.622)	
Slayton OIl Corporation		10. FIELD OR WILDCAT NAME Cha Cha Gallup	
3. ADDRESS OF OPERATOR P.O. Box 150, farmington, N. Mex.		11. SEC., T., R., M., OR BLK. AND SURVEY OR	
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 1650' AT TOP PROD. INTERVAL: FNL, 990FEL. AT TOTAL DEPTH:		AREA	
		sec. 21-T29N-14W	
		12. COUNTY OR PARISH San Juan	N. Mex.
		14. API NO.	
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA		none assigned	
		15. ELEVATIONS (SHOW DF, KDB, AND WD)	
REQUEST FOR	APPROVAL TO: SUBSEQUENT REPORT OF:	5251' KDB	
SHOOT OR ACI REPAIR WELL PULL OR ALTE MULTIPLE COM CHANGE ZONE ABANDON* (other) re	R CASING DEC 09	MANAGEMENT	ultiple completion or zone 330.)
including e	PROPOSED OR COMPLETED OPERATIONS (Clearly stat stimated date of starting any proposed work. If well is denoted true vertical depths for all markers and zones pertinents.)	lirectionally drilled, give sub	give pertinent dates, surface locations and
11-30-83	Rig up Farmington Well Ser. Lower tubing and touch fill at 4850 kb. Come out of hole. Set retreivable bridge plug at 4799'.		
12-1-83	Run cement bond log and correlation log. Good cement to 3900'. Shot 18 holes 4707-89. Ran 150 Joints 2 7/8" tubing with packer set at 4612 kb. Fill annulus with water. Treat with 500 gal. 7½ % Hcl followed by 1225 bbls. 20# gelled 190 kcl water containing 61,865 lbs. of 20-40 sand. ATP 3900 psi, AIR 22 bpm.		
12-2-83	Check sand level, no fill. Swabbed two runs through 2 7/8" tubing. Recovered 37 BF. Reverse circulated some sand. Swabbed 100 bf total.		

APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

TITLE Production Mgr. DATE 12-7-83 1983

TITLE Production Mgr. DATE 12-7-83 1983

TITLE Production Mgr. DATE FARMINGION RESOURCE OF APPROVAL, IF ANY:

12-3-83 SIP 20#, Fluid level 1200' Swabbed 50 bf., lowered fluid to 4600'.
Reverse circulated app. 20 feet of sand. Pulled packer and bridge plug.
*See Instructions on Reverse Side

12-5-83 Ran 4785' of 2 3/8 thing with seating nipple. Well pumping.