

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Send instructions on re-verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

14-20-603-2200

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Navajo

7. UNIT AGREEMENT NAME

NW Cha Cha

8. FARM OR LEASE NAME

NW Cha Cha Unit

9. WELL NO.

21-30 ~~72~~ 1

10. FIELD AND POOL, OR WILDCAT

Cha Cha Gallup

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 20-29N-14W NMPM

12. COUNTY OR PARISH 13. STATE

San Juan

N. M.

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
Humble Oil & Refining Company

3. ADDRESS OF OPERATOR
P. O. Box 120, Denver, Colorado 80201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
At surface

NE NW (660' FNL, & 2210' FWL) of Sec. 20

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5201' KB

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

9-23-72 Spot 10 sack cement plug from 4677-4577
Spot 10 sack cement plug from 3600-3500
9-25-72 Spot 15 sack cement plug @ 2150 inside 4½" casing
Perf 4 holes @ 900'. Pump 35 sacks cement plug from 900' to 340 inside and outside 4½" casing.
9-26-72 Perf 4 holes @ 550'. Pump 35 sacks cement plug from 550 to 450 inside and outside 4½" casing.
9-28-72 Squeeze 35 sxs cement down 4½" x 3 5/8" annulus
9-29-72 Installed regulation dry hole marker and cleaned location for inspection. Intervals between plugs filled with gelled mud.

CC: 2-New Mexico Oil Conservation Commission
1-Minerals Supervisor-Navajo Tribe
1-Midland



18. I hereby certify that the foregoing is true and correct

SIGNED J. Roy Dorrough

TITLE District Superintendent

DATE Jan 17 1973

(This space for Federal or State office use)

APPROVED BY _____

TITLE _____

DATE _____

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side