

FIELD TRIP REPORT

J	I	H
N	S	A.
I	C.	O
S	I	U
P	F.	R
E	I	Q
C	C.	U
L	L.	A.
A	T	R
S	I	T
I	F	E
C	I	R
T	C	S
O	P	O
N	E	S

Name Ennie Busch Date 5-11-87 Miles 59 District 3
 Time of Departure 7:00 A.M. Time of Return 5:00 P.M. Car No. SP 7378

In the space below indicate the purpose of the trip and the duties performed, listing wells or leases visited and any action taken.

Signature _____

PR	F. 19	<p>Trip to the 29N-13W area to continue plugging operations on the Culpepper #1. moved Big A well Service Company onto the location, set anchors, rigged up, picked up survey and load ⁶ 6^{1/2}" Drill collar, 4^{1/2}" x 2' bit stuck and 6^{1/4}" bit, commenced drilling on boulders and wood. First jt. of 8^{5/8}" casing case parted and was re-welded. Drilg. at 40° SDFN.</p>												
		<table border="1"> <tr> <td><u>Mileage</u></td> <td><u>Per Diem</u></td> <td><u>Hours</u></td> </tr> <tr> <td>UIC _____</td> <td>UIC _____</td> <td>UIC _____</td> </tr> <tr> <td>RFA <u>59</u></td> <td>RFA <u>6.00</u></td> <td>RFA <u>10</u></td> </tr> <tr> <td>Other _____</td> <td>Other _____</td> <td>Other _____</td> </tr> </table>	<u>Mileage</u>	<u>Per Diem</u>	<u>Hours</u>	UIC _____	UIC _____	UIC _____	RFA <u>59</u>	RFA <u>6.00</u>	RFA <u>10</u>	Other _____	Other _____	Other _____
<u>Mileage</u>	<u>Per Diem</u>	<u>Hours</u>												
UIC _____	UIC _____	UIC _____												
RFA <u>59</u>	RFA <u>6.00</u>	RFA <u>10</u>												
Other _____	Other _____	Other _____												

TYPE INSPECTION
PERFORMEDINSPECTION
CLASSIFICATIONNATURE OF SPECIFIC WELL
OR FACILITY INSPECTED

H - Housekeeping
 P - Plugging
 C - Plugging Cleanup
 T - Well Test
 R - Repair/Workover
 F - Waterflow
 M - Mishap or Spill
 W - Water Contamination
 O - Other

U - Underground Injection Control - Any inspection of or related to injection project, facility, or well or resulting from injection into any well. (SWD, 2ndry injection and production wells, water flows or pressure tests, surface injection equipment, plugging, etc.)
 R - Inspections relating to Reclamation Fund Activity
 O - Other - Inspections not related to injection or The Reclamation Fund
 E - Indicates some form of enforcement action taken in the

D - Drilling
 P - Production
 I - Injection
 C - Combined prod. inj. operations
 S - SWD
 U - Underground Storage
 G - General Operation
 F - Facility or location
 M - Meeting
 O - Other

FIELD TRIP REPORT

J I N S P E C T I O N	C L A S S I F I C A T I O N	F A. C I L I T Y	H O U R S	Q U A R T E R
				H O U R S

Name Eraile Burch Date 5-13-87 Miles 59 District 3
 Time of Departure 7:00 A.M. Time of Return 5:00 P.M. Car No. OF 7378

In the space below indicate the purpose of the trip and the duties performed, listing wells or leases visited and any action taken.

Signature _____

PRF 100

Trip to the 29W-13W area to continue plugging operations on the Culpepper #1.

Dug & Cleaning out joints, boulders and weed to ~~120'~~ 60', lost circulation, 400 bbls. SDFN

Mileage

UIC _____

RFA 59

Other _____

Per Diem

UIC _____

RFA 6.00

Other _____

Hours

UIC _____

RFA 10

Other _____

TYPE INSPECTION
PERFORMEDINSPECTION
CLASSIFICATIONNATURE OF SPECIFIC WELL
OR FACILITY INSPECTED

H - Housekeeping
 P - Plugging
 C - Plugging Cleanup
 T - Well Test
 R - Repair/Workover
 F - Waterflow
 M - Mishap or Spill
 W - Water Contamination
 O - Other

U - Underground Injection Control - Any inspection of or related to injection project, facility, or well or resulting from injection into any well. (SWD, 2ndry injection and production wells, water flows or pressure tests, surface injection equipment, plugging, etc.)
 R - Inspections relating to Reclamation Fund Activity
 O - Other - Inspections not related to injection or The Reclamation Fund
 E - Indicates some form of enforcement action taken in the

D - Drilling
 P - Production
 I - Injection
 C - Combined prod. inj. operations
 S - SWD
 U - Underground Storage
 G - General Operation
 F - Facility or location
 M - Meeting
 O - Other

NEW MEXICO OIL CONSERVATION COMMISSION
FIELD TRIP REPORT

IN-SPE-C-TION	C-LA-S-SI-FI-CAT-I-O-N	F-A-C-I-LIT-Y	H-O-U-R-S	Q-U-A-R-T-E-R	H-O-U-R-S
---------------	------------------------	---------------	-----------	---------------	-----------

Name Emude Busch Date 5-14-87 Miles 59 District 3
 Time of Departure 7:00 A. M. Time of Return 5:00 P. M. Car No. NE 2378

In the space below indicate the purpose of the trip and the duties performed, listing wells or leases visited and any action taken.

Signature _____

P R F	10	<p>Trip to the 29N - 13W area to continue plugging operations on the Culpepper #1. Drilled & cleaning out junk, boulders and wood to 225' lost circulation, 200661s. Rigged down, moved rig off location.</p> <p>* Contractor did not fulfill requirements and decided to break contract.</p> <p>* Breached contract, did not complete job.</p>		
		<u>Mileage</u> UIC _____ RFA <u>59</u> Other _____	<u>Per Diem</u> UIC _____ RFA <u>6.00</u> Other _____	<u>Hours</u> UIC _____ RFA <u>10</u> Other _____

TYPE INSPECTION
PERFORMED

INSPECTION
CLASSIFICATION

NATURE OF SPECIFIC WELL
OR FACILITY INSPECTED

- I - Housekeeping
- P - Plugging
- C - Plugging Cleanup
- T - Well Test
- R - Repair/Workover
- F - Waterflow
- M - Mishap or Spill
- W - Water Contamination
- O - Other

- U - Underground Injection Control - Any inspection of or related to injection project, facility, or well or resulting from injection into any well. (SWD, 2ndry injection and production wells, water flows or pressure tests, surface injection equipment, plugging, etc.)
- R - Inspections relating to Reclamation Fund Activity
- O - Other - Inspections not related to injection or The Reclamation Fund
- E - Indicates some form of enforcement action taken in the

- D - Drilling
- P - Production
- I - Injection
- C - Combined prod. inj. operations
- S - SWD
- U - Underground Storage
- G - General Operation
- F - Facility or location
- M - Meeting
- O - Other

FIELD TRIP REPORT

INSP	C	F
EC	A.	H
ECT	O	O
EC	U	U
EC	R	Q
EC	I	A.
EC	L	C.
EC	S	A.
EC	I	O.
EC	F	U.
EC	I	R.
EC	C	E.
EC	T	R.
EC	A	E.
EC	C	R.
EC	T	S.

Name Eric Busch Date 5-15-87 Miles 59 District 3
 Time of Departure 7:00 A.M. Time of Return 4:00 P.M. Car No. OF 7378

In the space below indicate the purpose of the trip and the duties performed, listing wells or leases visited and any action taken.

Signature _____

P R F 9 - Trip to the 29N-13W Area to restore ^{Cal Pepper #1} well site to original condition. ~~and wait~~
 moved in Navajo Oil Field Service to
~~fill in~~ ^{the} well temporary cap on
 well casing and fill in with gravel
 and dirt around and over well. ~~the~~
 Returned down ~~the~~ to the well
 and to original condition to wait
 on next bidder to plug the well.

Mileage	Per Diem	Hours
UIC _____	UIC _____	UIC _____
RFA <u>59</u>	<u>600</u>	<u>9</u>
Other _____	Other _____	Other _____

TYPE INSPECTION PERFORMED	INSPECTION CLASSIFICATION	NATURE OF SPECIFIC WELL OR FACILITY INSPECTED
H - Housekeeping	U - Underground Injection Control - Any inspection of or related to injection project, facility, or well or resulting from injection into any well. (SWD, 2ndry injection and production wells, water flows or pressure tests, surface injection equipment, plugging, etc.)	D - Drilling
P - Plugging	R - Inspections relating to Reclamation Fund Activity	P - Production
C - Plugging Cleanup	O - Other - Inspections not related to injection or The Reclamation Fund	I - Injection
T - Well Test	E - Indicates some form of enforcement action taken in the	C - Combined prod. inj. operations
R - Repair/Workover		SWD
F - Waterflow		Underground Storage
M - Mishap or Spill		G - General Operation
W - Water Contamination		F - Facility or location
O - Other		H - Meeting
		O - Other