



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6170 Fax (505) 334-6170

GARY E. JOHNSON
GOVERNOR

JENNIFER A. SALISBURY
CABINET SECRETARY

July 29, 1996

Dolores Diaz
Meridian Oil Inc
PO Box 7289
Farmington NM 87401

RE: Wood #3 H-17-29N-10W, API # 30-045-08350

Dear Dolores:

As the enclosed copy of the 1996 Bradenhead test indicates, the referenced well probably has a small casing leak. In order to comply with Rule 108, prevent waste, protect fresh water and protect the environment, you are hereby directed to initiate remedial activity prior to January 16, 1997.

Sincerely,

Johnny Robinson
Deputy O&G Inspector

JR/sh

cc: well file

STATE OF NEW MEXICO
ENERGY and MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
1000 Rio Brazos Road
Aztec, New Mexico

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-8-96 Operator MERIDIAN OIL CO.

Lease Name WOOD Well No 3 Unit H Sec. 17 Twp. 029N Rge. 010W

Pressure (Shut-in/Flowing) Dwt Tubing 68 Intermediate U/A CASING 108 BRADENHEAD 96

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME:	PRESSURES:		FLOWED:	
	INTERMEDIATE	CASING	BRADENHEAD	INTERMEDIATE
5 Min.		<u>108</u>	<u>Light</u> Steady Flow <u>X</u>	
10 Min.		<u>107</u>	Surges	
15 Min.		<u>111</u>	Down to Nothing	
20 Min.		<u>112</u>	Nothing	
25 Min.		<u>111</u>	Gas <u>X</u> & <u>0:1</u>	
30 Min.		<u>110</u>	Gas & Water	
			Water	

If Bradenhead flowed water check description below:

Clear _____
Fresh _____
Salty _____
Sulfur _____
Black _____

Remarks: Braden head Blew to a light whisper
then Flowed about 3 gal of Oil then
Back to a light ^{Blow} of Gas

By Mark Mc

LEASE OPERATOR
position

Witness _____
JUL 20 1996

DPNO 50403A

30-45-08350