

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY FRANK A. SCHULTZ - Box 728 - Farmington, New Mexico.
(Address)

LEASE State WELL NO. 8-16 UNIT A S 16 T 29-N R 10-W
DATE WORK PERFORMED Nov. 24 & 25, 1957 POOL Aztec P. C.

This is a Report of: (Check appropriate block) ☐ Results of Test of Casing Shut-off
☒ Beginning Drilling Operations ☐ Remedial Work
☐ Plugging ☐ Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.
Spudded well at 10:00 A.M. on November 24, 1957. On November 25, 1957, after drilling to 106' RKB., set 3 joints (96') of 8-5/8" OD 24# J-55 casing at 106' with 70 sacks cement.

Circulated cement to surface and moved off. Will continue drilling with rotary tools at later date.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____
Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____
Perf Interval (s) _____
Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

	BEFORE	AFTER
Date of Test	_____	_____
Oil Production, bbls. per day	_____	_____
Gas Production, Mcf per day	_____	_____
Water Production, bbls. per day	_____	_____
Gas-Oil Ratio, cu. ft. per bbl.	_____	_____
Gas Well Potential, Mcf per day	_____	_____
Witnessed by _____		

(Company)

OIL CONSERVATION COMMISSION

Name Original Signed Emery C. Arnold
Title Supervisor Dist. # 3
Date DEC 5 1957

I hereby certify that the information given above is true and complete to the best of my knowledge.
Name *C. Beeson Neal*
Position C. Beeson Neal, Agent in Farmington
Company Frank A. Schultz



OIL CONSERVATION COMMISSION

100

NO. 50, 1954

1. The first step in the process is to identify the problem or issue that needs to be addressed. This involves gathering information and understanding the context of the problem.

FILE

✓