

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency _____

Navajo

Allottee _____

Lease No. 11-20-603-1019

2		
	16	

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<input checked="" type="checkbox"/>		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 29, 1961

Well No. 18 is located 660 ft. from N line and 1960 ft. from W line of sec. 16
NE 1/4 Section 16 29N 18W 100M
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wilcox San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5169' ft. Ungraded Ground.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

TD 502'.

It is intended to plug and abandon well as follows: 100' plug in surface which covers top of Gallup formation. A regulation dry hole marker will be placed in top of cement. Location will be cleared.

Verbal approval by Mr. Bear to Mr. Robert Van Horn on 11-28-61.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced

Company Humble Oil & Refining Company

Address P. O. Box 3002

Durango, Colorado

By COPY (ORIGINAL SIGNED) B. M. BRADLEY
B. M. Bradley
Title Dist. Supt.