



(SUBMIT IN TRIPLICATE)
**UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY**

Land Office Santa Fe
Lease No. SF-076958
Unit H

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 17, 1956

Well No. 5 Bare is located 890 ft. from S line and 1850 ft. from W line of sec. 10

SS/SW Section 10
(1/4 Sec. and Sec. No.)

T-29-N, R-10-W
(Twp.) (Range)

N.M.P.M.
(Meridian)

Artes Pictured Cliffs
(Field)

San Juan
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 5018 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

T.D. 2292'. Perforated from 2206-46 with 4 shots per foot. Sand-water frac with 34,901 gallons water, 9,199 gallons flush, 10,000 lbs. sand. Breakdown pressure 1200 lbs., Treating pressure 1050 lbs., Final pressure 300 lbs., Injection Rate 54.4 barrels per minute. Ran 2214' of 1" tubing landed at 2224'. S I G 4-14-56.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company ARTEC OIL & GAS COMPANY

Address P. O. Box 786

Farrington, New Mexico

By Joe C. Salmon
Title Drilling Superintendent

