

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency Havas
(Window Rock)
Allottee _____
Lease No. 14-20-603-1049

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<input checked="" type="checkbox"/>		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 21, 1964

Well No. 2 is located 130 ft. from SW line and 660 ft. from E line of sec. _____
(SE 1/4) 8 29 North 18 West N7W
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Shiprock San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the ~~subsurface~~ ground above sea level is 5100 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Will plan to run cement plug from bottom to top and install dry hole marker

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company _____
Address Santa Fe, New Mexico

By Original signed/SAE E. MEDICE
Title OPERATOR

