



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-B558.4.
Form Approved.

Land Office Santa Fe
Lease No. SF 076958
Unit Hare

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	XX
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 9, 1962

Hare

Well No. 12-D is located 1500 ft. from [N] line and 1070 ft. from [E] line of sec. 10

NE 1/4 Section 10

(1/4 Sec. and Sec. No.)

T-29N

(Twp.)

R-10W

(Range)

N.M.P.M.

(Meridian)

Basin Dakota

(Field)

San Juan

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is 5835 ft. G.L.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

P.B.T.D.- 6679'

Sand-water fraced with 74,340 gals. water, 65,000# sand

Breakdown pr.- 1500#

Avg. treating pr.- 2700#

Avg. I.R.- 37 bpm

Maximum treating pr.-3000#

dropped 50 rubber ball sealers

Flushed with 130 Hols.

Instant shut in- 1300

5 min. shut in pr.-900

Ran 210 jts., 6627' of 2 3/8" tubing, landed at 6638'

Shut in for gauge.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Aztec Oil & Gas Company

Address Drewer # 570

Farmington, New Mexico

By ORIGINAL SIGNED BY JOE C. SALMON

Joe C. Salmon

Title District Superintendent