


(SUBMIT IN TRIPLICATE)

Indian Agency _____

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____

Lease No. **11-02-603-2019**



SUNDRY NOTICES AND REPORTS ON WELLS

| | |
|----------------------------------------------------|-------------------------------------------------|
| NOTICE OF INTENTION TO DRILL..... | SUBSEQUENT REPORT OF WATER SHUT-OFF..... |
| NOTICE OF INTENTION TO CHANGE PLANS..... | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING..... |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF..... | SUBSEQUENT REPORT OF ALTERING CASING..... |
| NOTICE OF INTENTION TO REDRILL OR REPAIR WELL..... | SUBSEQUENT REPORT OF REDRILLING OR REPAIR..... |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE..... | SUBSEQUENT REPORT OF ABANDONMENT..... |
| NOTICE OF INTENTION TO PULL OR ALTER CASING..... | SUPPLEMENTARY WELL HISTORY..... |
| NOTICE OF INTENTION TO ABANDON WELL..... | |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Savage _____ **Sept. 16,** _____, 19 **61**

Well No. **1** is located **165** ft. from **[N]** line and **165** ft. from **[E]** line of sec. **8**
ENHRS sec. **8** **29 N.** **18 W.** **N.M.P.**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat **Santa Juan** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **5277** ft. **574.**

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

TD 150 ft. Well has been abandoned and hole filled with cement, top to bottom. 4-foot marker placed at surface.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Sun Fire Oil, Inc.**
 Address **515 Main Bldg.**
Albuquerque, New Mexico
 By **Frank A. King**
 Title **Vice President**