



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 070197
Unit S/R

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

U.S. GEOLOGICAL SURVEY
OFFICE, NEW MEXICO

October 9, 1962

J. Glenn Turner - Eye

Well No. 4-1 is located 1,730 ft. from S line and 1,733 ft. from E line of sec. 4

SW/4 Section 4
(1/4 Sec. and Sec. No.)

T 22-North- R 10-West
(Twp.) (Range)

N.M.P.M.
(Meridian)

Basin Dakota - Blanco N.Y.
(Field)

San Juan County
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 5,869 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

October 7, 1962. Spudded well at 11:45 A.M.

Drilled 12-1/4" hole to 293'. Run 9 joints 8-1/8" 54 J-95, STC casing. Tens pattern show on bottom joint. 2 centralizers on bottom 2 joints. Spot welded collars and lubricated pins on bottom 2 joints.

Landed at 293'.

Cemented with 200 sacks cement with 2 1/2 Cuft 2. Displaced cement with 18.5 cu. Circulated approximately 30 sacks cement.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company J. Glenn Turner

Address P. O. Box 728

Farmington, New Mexico

By G. Deane Neal, Agent in Farmington
Title _____