



STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE

GARREY CARRUTHERS
GOVERNOR

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178

September 9, 1987

Meridian Oil, Inc.
P.O. Box 2489
Farmington, NM 87499

Re: Lloyd B #3 E-01-29N-11W

Gentlemen:

The regularly scheduled bradenhead test on the referenced well indicates a casing failure.

In order to comply with Rule 108, prevent waste and protect fresh water, you are hereby directed to initiate immediate remedial activity.

Yours truly,

A handwritten signature in cursive script, appearing to read "Charles Gholson".

Charles Gholson
Deputy Oil & Gas Inspector

CG/dj

xc: Well File

02-14

OIL CONSERVATION DIVISION
1000 Rio Brazos Road
Aztec, New Mexico

BRADENHEAD TEST REPORT
(Submit 2 copies to above address)

Date of Test 8-6-87 Operator MERIDIAN OIL

Lease Name Lloyd B Well No. 3 Location U E Sec. 01 Twp. 29 Rge. 11

Pressure (Shut-in or Flowing) Dwt Tubing — Intermediate — Casing 99 Bradenhead 99

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH.

TIME:	PRESSURES:	
	INTERMEDIATE	CASING
5 Min.		<u>23</u>
10 Min.		<u>22</u>
15 Min.		<u>21</u>
20 Min.		<u>21</u>
25 Min.		<u>24</u>
30 Min.		<u>24</u>

	BRADENHEAD FLOWED:	INTERMEDIATE FLOWED:
Steady Flow	<u>✓</u>	
Surges		
Down to Nothing		
Nothing		
Gas	<u>✓</u>	
Gas & Water		
Water		

If Bradenhead flowed water check description below:

Clear
Fresh
Salty
Sulfur
Black

Remarks: AFTER 25 min. Pressure
INCREASED.

By Gabe Archibegue

LEASE OPERATOR
Position

Witness

SEP 02 1987