


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency _____
Allottee _____
Lease No. **1-99-13**



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

10-11-55

19

Well No. **12-372** is located **2640** ft. from **N** line and **990** ft. from **E** line of sec. **6**
114 (1/4 Sec. and Sec. No.) **298** (Twp.) **204** (Range) **14371** (Meridian) **N.M.**
Wildcat (Field) **San Juan** (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **5323** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mud and cementing points, and all other important proposed work)

Spooled 10-8-55
Completed 10-11-55
T.D.-1042
Top De Kate 830
Top Morris 1090
25 lb cement plug 900 to 750'
10 mesh cement plug at surface
Pits filled; loss time cleaned up and regulation marker set



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Continental Oil Co.**

Address **Box 1896**

Peru, W.Va.

By

Wilbur L. Durr

Title

Geologist Supervisor 12/1-4

1871