


Form 10-10-1  
U.S. G.S.



(SUBMIT IN TRIPPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe  
Lease No. 078578  
Well 5/2 Section 21

SUNDRY NOTICES AND REPORTS ON WELLS

RECEIVED

AUG 1962

|                                                       |    |                                            |  |
|-------------------------------------------------------|----|--------------------------------------------|--|
| NOTICE OF INTENTION TO DRILL                          |    | SUBSEQUENT REPORT OF WATER SHUT-OFF        |  |
| NOTICE OF INTENTION TO CHANGE PLANE                   |    | SUBSEQUENT REPORT OF SINKING OR ACIDIZING  |  |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF            |    | SUBSEQUENT REPORT OF ALTERING CANNING      |  |
| NOTICE OF INTENTION TO <del>ABANDON</del> REPAIR WELL | XX | SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR |  |
| NOTICE OF INTENTION TO SINK OR ACIDIZE                |    | SUBSEQUENT REPORT OF ABANDONMENT           |  |
| NOTICE OF INTENTION TO SILL OR ALTER CANNING          |    | SUPPLEMENTARY WELL HISTORY                 |  |
| NOTICE OF INTENTION TO ABANDON WELL                   |    |                                            |  |

U. S. GEOLOGICAL SURVEY  
FARMINGTON, NEW MEXICO

(SIGNATURE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 2, 1962

Well No. 40 is located 1650 ft. from (N) line and 1825 ft. from (E) line of sec. 21


NE 1/4 Section 21 T-20-N R-2-W SE 1/4  
(of Sec. and Twp. No.) (Twp.) (Range) (Section)  
Blanco Mesaverte San Juan New Mexico  
(Name) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5819 ft. D. F.

DETAILS OF WORK

State nature of and reported depths to objectives, casing shoe logs, weights, and lengths of proposed casings; indicate working logs, cementing patterns, and all other important proposed work.

Broken head has pressure, propose to perforate 7" at 1100; break circulation with mud and follow with approximately 800 sacks of cement to seal off source of pressure.



I understand that this plan of work must be approved in writing by the Geological Survey before operations are begun.

Company Polk-Taylor Oil Corporation

Address P. O. Drawer 2190

Farmington, New Mexico

Original signed by  
By G. T. HIGGINBOTHAM  
G. T. Higginbotham  
Title District Superintendent

U.S. G.S. FORM 10-10-1