


STATE OF NEW MEXICO
OIL CONSERVATION
COMMISSION

DISTRICT NO. 3
Phone 99 P. O. Box 697
AZTEC, NEW MEXICO

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 07980
Unit Block 1



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	☒
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 3-A is located 800 ft. from S line and 800 ft. from W line of sec. 4
SW 1/4 Section 4 (1/4 Sec. and Sec. No.) SW (Twp.) SW (Range) N. M. P. M. (Meridian)
Elizabethtown (Field) Santa Fe (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6000 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Casing head set at 2750' on June 1, 1951, failed to hold water out of casing.

June 10, 1951, set Cal-sol plug at 2750' and perforated with four shots at 2750'.

June 11, 1951, set Halliburton Retainer at 2711' and squeezed with 150 sacks Ideal Regular through perforations.

June 12, 1951, squeezed perforations with 200 sacks Ideal Regular Cement.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company SAN JUAN PETROLEUM COMPANY

Address 102 1/2 North Court Avenue

Farmington, New Mexico

By


E. J. Coal

Title

E. J. Coal
Petroleum Engineer

Land Office _____
 Lease No. _____
 Unit _____

(SUBMIT IN TRIPlicate)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY



SUNDRY NOTICES AND REPORTS ON WELLS

REPORT OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
REPORT OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
REPORT OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
REPORT OF INTENTION TO RE-DRILL OR RE-PAVE WELL	SUBSEQUENT REPORT OF RE-DRILLING OR RE-PAVING
REPORT OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
REPORT OF INTENTION TO PULL OR WATER CASING	SUPPLEMENTARY WELL HISTORY
REPORT OF INTENTION TO ABANDON WELL	

(Indicate where by contract, assignment or report, notice or other basis)

The _____ is located _____ ft. from _____ line and _____ ft. from _____ line of sec. _____

_____ (Owner)
 _____ (Operator)
 _____ (Geological Survey)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

The purpose of this report is to give a complete and accurate description of the work done on the well during the period covered by the report. It should include a description of the well, the equipment used, the methods employed, and the results obtained. It should also include a description of the work done on the well during the period covered by the report.

The work done on the well during the period covered by the report was _____

The results of the work done on the well during the period covered by the report were _____

I understand that this plan of work is being received by the Geological Survey for review and approval. I understand that the plan of work is being received by the Geological Survey for review and approval.

Company _____
 Address _____

By _____
 Title _____