

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY PURCO DEVELOPMENT, INC., 107 West Chase, Artee, New Mexico
(Address)

LEASE State WELL NO. 10 UNIT S 2 T 30N R 30W
DATE WORK PERFORMED 8-30-55 POOL Blanco Mesa Verde

This is a Report of: (Check appropriate block) ☐ Results of Test of Casing Shut-off
☐ Beginning Drilling Operations ☐ Remedial Work
☐ Plugging ☒ Other 5 1/2" Casing Detail

Detailed account of work done, nature and quantity of materials used and results obtained.

Run 100 Jts, 5170.55' MD, of 5 1/2" 15.5# 8 rd thd J-55 casg w/Baker Elliott and
Tomas pattern shoe. cement w/150 sac reg. cement, 30 sac stratoconcrete and 6%
gel. Poor circulation. Work comp. @ 10:00 P.M. 8-30-55.

Results of temp. survey: top of cement at 3080'.

Tested casing w/1500# press. Test OK.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____
Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____
Perf Interval (s) _____
Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

Date of Test _____
Oil Production, bbls. per day _____
Gas Production, Mcf per day _____
Water Production, bbls. per day _____
Gas-Oil Ratio, cu. ft. per bbl. _____
Gas Well Potential, Mcf per day _____
Witnessed by _____

BEFORE

AFTER



OIL CONSERVATION COMMISSION

Name Timothy C. [Signature]
Title Oil and Gas Inspector Dist. #3.
Date SEP 6 1955

I hereby certify that the information given
above is true and complete to the best of
my knowledge.

Name A. D. Brown [Signature]
Position Prod. Engr.
Company PURCO DEVELOPMENT, INC.
107 West Chase, Artee, New Mexico

OIL CONSERVATION COMMISSION		
AZTEC DISTRICT OFFICE		
No. Copies Received		6
DISTRIBUTION		
	NO. COPIES	
Operator	4	
Santa Fe	1	
Proration Office		