#### TABULATION OF DEVIATION TESTS

#### TENNECO OIL COMPANY

### FLORANCE #86

DPETH	INCLINATION
124'	1/4°
632'	1/4°
1 <b>3</b> 35'	1-1/2°
2460'	3/4°

# $\underline{A} \ \underline{F} \ \underline{F} \ \underline{I} \ \underline{D} \ \underline{A} \ \underline{V} \ \underline{I} \ \underline{T}$

THIS IS TO CERTIFY that to the best of my knowledge the above tabulation details the deviation test taken on TENNECO OIL COMPANY'S FLORANCE #86, Blanco Pictured Cliffs Field, located in Section 26, T-29-N, R-9-W, San Juan County, New Mexico.

THE STATE OF COLORADO) COUNTY OF LA PLATA

BEFORE ME, the undersigned authority, on this day personally appeared Harold C. Nichols known to me to be Senior Production Clerk for Tenneco Oil Company and to be the person whose name is subscribed to the above statement, who, being by me duly sworn on oath, states that he has knowledge of the facts stated herein and that said statement is true and correct.

SUBSCRIBED AND SWORN TO before me, a Notary Public in and for said County and State this 13th day of April, 1966.

My commission expires June 28, 1969.

MARIE L. POER

Product, 100a P. O. Box 1014 Durango, Colorado La Piata Colorado

## Distribution:

1 Copy - New Mexico Oil Conservation Commission

l Copy - Continental l Copy - File