
DEC E O las

Meter Number: 75549
Location Name: DJ SIMMONS ET AL #11
Location: TN-29 RG-09

SC-29 UL-H

2 - Federal NMOCD Zone:OUTSIDE Hazard Ranking Score:00



RATIONALE FOR RISK-BASED CLOSURE OF PRODUCTION PITS LOCATED OUTSIDE OF THE VULNERABLE ZONE IN THE SAN JUAN BASIN

This production pit location was ranked according to the criteria in the New Mexico Oil Conservation Division's Unlined Surface Impoundment Closure Guidelines and received a ranking score of zero. The estimated depth to groundwater is greater than 100-feet beneath ground surface (bgs), the pit is not in a well head protection area, and there are no surface water bodies within 1,000 horizontal feet of the pit location.

The primary source, discharge to the pit has been removed. There has been no discharge to the pits for at least 4 years and the pits have been closed for at least one year.

Each pit was backfilled with clean soil and graded in a manner to divert precipitation away from the excavated area. Minimal infiltration of rainfall is expected. Any rainfall that does infiltrate the ground surface must migrate through clean backfill before reaching the residual hydrocarbons.

There is no source material at the ground surface, so direct contact of hydrocarbons with livestock and the populous is not likely.

In general, outside of the vulnerable area and alluvial valleys, bedrock material is generally encountered within 20 feet of the ground surface. Bedrock material in the San Juan Basin consists of interbedded sandstones, shales and clays. According to Freeze and Cherry, 1979, the hydraulic conductivity of the bedrock material are as follows:

Sandstone 10^{-9} to 10^{-13} cm/sec Shale 10^{-12} to 10^{-16} cm/sec Clay 10^{-12} to 10^{-15} cm/sec

Based on this information, the residual hydrocarbons should not migrate to groundwater.

Natural process (bioremediation) are degrading the residual hydrocarbon to carbon dioxide and water and will continue until the source is gone, therefore minimizing any impact to the environment.

Based on the above information, it is highly unlikely that any source material will impact groundwater or ever find an exposure pathway to affect human health and therefore El Paso Field Services Company (EPFS) requests closure of this pit location.



FIELD PIT SITE ASSESSMENT FORM

GENERAL	Meter: 75549 Location: _DJ SIMMONS ET AL #11 Operator #: _8043 _ Operator Name: DJ SIMMONS P/L District: _8LANCO Coordinates: Letter: H_ Section 29 Township: _29 Range: _9 Or						
SITE ASSESSMENT	NMOCD Zone: (From NMOCD Maps) Inside Outside Outside (1) Fee (3) Outside Outside (2) Maps) Depth to Groundwater Less Than 50 Feet (20 points) Greater Than 100 Ft (0 points) Wellhead Protection Area: Is it less than 1000 ft from wells, springs, or other sources of fresh water extraction?, or; Is it less than 200 ft from a private domestic water source? (1) YES (20 points) Horizontal Distance to Surface Water Body Less Than 200 Ft (20 points) (2) Greater Than 1000 Ft (0 points) (3) Name of Surface Water Body (Surface Water Body: Perennial Rivers, Major Wash, Streams, Creeks, Irrigation Canals, Ditches, Lakes, Ponds) Distance to Nearest Ephemeral Stream (1) < 100'(Navajo Pits Only) (2) > 100' TOTAL HAZARD RANKING SCORE: O POINTS						
REMARINS	Remarks: ONLY PIT ON LOCATION. PIT IS DRY. LOCATION IS ON A MESA SOUTH OF SULLIVAN RD. PEDLINE AND TOPO CONFIRMED LOCATION IS						
RE	OUTSIDE V.Z. PUSH IN						

	ORIGINAL PIT LOC Original Pit : a) Degrees from North <u>240</u>	P° Footage from Weilhead 66'
ORIGINAL PIT LOCATION	b) Length: Width:	
	Ko 13'	
REMARKS	Remarks: TOOK PICTURES AT 12:47 P.M. END DUMP	
	Completed By:	
	Loot Champson	5-14-94
	Signature ¹	Date

FIELD PIT REMEDIATION/CLOSURE FORM

GENERAL	Meter: 75549 Location: OJ Simnons Et Al #11 Coordinates: Letter: 11 Section 29 Township: 29 Range: 9 Or Latitude Longitude Date Started: 7-27-94 Run: 03 44							
FIELD OBSERVATIONS	Sample Number(s): Feet Sample Depth: Feet Final PID Reading PID Reading Depth Feet Yes No Groundwater Encountered							
KS CLOSURE	Remediation Method: Excavation							
	Other Facility Name: Pit Closure Date: 7-27-94 Pit Closed By: BE Remarks: £PNG lines marked Soil Ergy. 54 Black Slight							
REMARKS	Signature of Specialist: Morgon Xillian (SP3191) 03/16/94							



FIELD SERVICES LABORATORY ANALYTICAL REPORT PIT CLOSURE PROJECT - Soil

SAMPLE IDENTIFICATION

	Field ID		Lab ID			
SAMPLE NUMBER: mx 188			945777			
MTR CODE SITE NAME:		N/A :233				
SAMPLE DATE TIME (Hrs):	7-27-94					
SAMPLED BY:	N/A					
DATE OF TPH EXT. ANAL.:			7/28/94			
DATE OF BTEX EXT. ANAL.:						
TYPE DESCRIPTION:		Water Time is			inc	
REMARKS:						
		RESULTS				
PARAMETER	RESULT	UNITS	QUALIFIERS			
			DF	Q	M(g)	V(ml)
BENZENE		MG/KG				
TOLUENE		MG/KG				
ETHYL BENZENE		MG/KG				
TOTAL XYLENES		MG/KG				
TOTAL BTEX		#iG/KG				
TPH (418.1)	16,000	MG/KG				28
HEADSPACE PID	161	PPM				
PERCENT SOLIDS	87.9	%				
he Surrogate Recovery was at	- TPH is by EPA Method 4	118.1 and BTEX is by EPA N % for this sample		was accep	table.	

OF = Dilution Factor Used

Annroved Bv:

J. J.

Date:

8/8/94

Test detak væte kreisketen sautet tom

Test detak for

This inc Encles and Petroleum Hydrocombone

in Wesen and Holl

Testing Flags detak Recombone

Pred detak Recombone

Pred

ILLEGIBLE