

C4939

District I
P.O. Box 1980, Hobbs, NM
District II
P.O. Drawer DD, Artesia, NM 88211

State of New Mexico
Energy, Minerals and Natural Resources Department

SUBMIT 1 COPY TO
APPROPRIATE
DISTRICT OFFICE
AND 1 COPY TO
SANTA FE OFFICE

RECEIVED
FEB - 8 2001

Approved
Olson
2/5/01
OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

RECEIVED
OIL CON. DIV.

1007 8 - 834

OIL CON. DIV. PIT REMEDIATION AND CLOSURE REPORT
DIST. 3

Operator: Amoco Production Company Telephone: (505) - 326-9200
Address: 200 Amoco Court, Farmington, New Mexico 87401
Facility Or: MARTINEZ GC G #1
Well Name _____
Location: Unit or Qtr/Qtr Sec A Sec 24 T 29N R 10W County SAN JUAN
Pit Type: Separator ___ Dehydrator ___ Other BLOW
Land Type: BLM __, State __, Fee ☒, Other _____

Pit Location: Pit dimensions: length 90', width 110', depth 3-5'
(Attach diagram) Reference: wellhead X, other _____
Footage from reference: 240
Direction from reference: 20 Degrees ☒ East North ☒
of
_____ West South _____

Depth To Ground Water: Less than 50 feet (20 points)
(Vertical distance from 50 feet to 99 feet (10 points)
contaminants to seasonal Greater than 100 feet (0 Points) 20
high water elevation of
ground water)

Wellhead Protection Area: Yes (20 points)
(Less than 200 feet from a private No (0 points) 0
domestic water source, or; less than
1000 feet from all other water sources)

Distance To Surface Water: Less than 200 feet / (20 points)
(Horizontal distance to perennial 200 feet to 1000 feet (10 points)
lakes, ponds, rivers, streams, creeks, Greater than 1000 feet (0 points) 20
irrigation canals and ditches)

RANKING SCORE (TOTAL POINTS): 40

Date Remediation Started: _____ Date Completed: 9/1/93Remediation Method: Excavation ☒ Approx. cubic yards 1,200
(Check all appropriate sections) Landfarmed ☒ Insitu Bioremediation _____

Other _____

Remediation Location: Onsite ☒ Offsite _____
(ie. landfarmed onsite,
name and location of
offsite facility)

General Description Of Remedial Action: _____

Excavation . GROUNDWATER IMPACTED .

Ground Water Encountered: No _____ Yes ☒ Depth 4'Final Pit: Sample location see Attached DocumentsClosure Sampling:
(if multiple samples,
attach sample results
and diagram of sample
locations and depths)Sample depth 4' (GROUNDWATER)Sample date 8/31/93 Sample time 1450

Sample Results

Benzene(ppm) _____

Total BTEX(ppm) _____


Field headspace(ppm) _____

TPH _____

Ground Water Sample: Yes ☒ No _____ (If yes, attach sample results)I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST
OF MY KNOWLEDGE AND BELIEFDATE 9/1/93

SIGNATURE

B. ShawPRINTED NAME
AND TITLEBuddy D. Shaw
Environmental Coordinator



ENVIROTECH LABS

5796 US HIGHWAY 64-3014 • FARMINGTON, NEW MEXICO 87401
PHONE: (505) 632-0615 • FAX: (505) 632-1865

EPA METHOD 8020 AROMATIC VOLATILE ORGANICS

Client:	Amoco	Project #:	92140
Sample ID:	Pit Water	Date Reported:	09-01-93
Laboratory Number:	5988	Date Sampled:	08-31-93
Sample Matrix:	Water	Date Received:	08-31-93
Preservative:	HgCl and Cool	Date Analyzed:	09-01-93
Condition:	Cool and Intact	Analysis Requested:	BTEX

Parameter	Concentration (ug/L)	Det. Limit (ug/L)
-----	-----	-----
Benzene	9.3	0.2
Toluene	7.8	0.5
Ethylbenzene	3.6	0.2
p,m-Xylene	52	0.6
o-Xylene	31.7	0.3


SURROGATE RECOVERIES:	Parameter	Percent Recovery
	-----	-----
	Trifluorotoluene	95 %
	Bromofluorobenzene	93 %


Method: Method 5030, Purge-and-Trap, Test Methods for Evaluating
Solid Waste, SW-846, USEPA, Sept. 1986

Method 8020, Aromatic Volatile Organics, Test Methods for
Evaluating Solid Waste, SW-846, USEPA, Sept. 1986

ND - Parameter not detected at the stated detection limit.

Comments: Martinez GC "G" No. 1 Blow Pit C4939


Analyst


Review

