



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4  
Approval expires 12-31-60.

Land Office **Santa Fe**  
Lease No. **SF 078931-B**  
Unit \_\_\_\_\_

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. **2** is located **1980** ft. from **122** line and **510** ft. from **E** line of sec. **31**  
**SE 1/4 Sec. 31** (1/4 Sec. and Sec. No.) **29 N** **13 W** **N.M.P.M.**  
**Cha Cha Gallup** (Field) **San Juan** (County or Subdivision) **New Mexico** (State or Territory)

The elevation of the **ground level** above sea level is **5863** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Running and cementing surface casing as follows:

Ran 4 joints 8-5/8" OD, 24#, J-55 casing and set at 144'. Cemented with 125 sacks cement and circulated to surface. Plug down 6:05 a.m. 5-5-61. WOC 8 hours. Pressure tested casing to 600 pounds for 30 minutes. Pressure held o.k.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Tenneco Corporation**

Address **P. O. Box 1714**

**Durango, Colorado**

By **L. B. Plumb**

Title **District Production Superintendent**