


(SUBMIT IN TRIPLICATE)

Land Office San JuanLease No. 27 57530-AUnit 2/2 Sec. 9UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 27, 1956

R.J. Moore
Well No. 5 is located 300 ft. from S line and 200 ft. from W line of sec. 9
SW 1/4 Sec. 9 (Twp.) 2N (Range) 107W (Meridian)
Blanco (Shipwreck) (Twp.) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 5000 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well spudded March 23, 1956.

Drilled to TD 226' Set 1, 3/4" 132' of 10 1/4" 30.75' Steel-cased Casing, landed at 214' cemented w/ 150 sacks. Casing was pressured to 500' for 1 hour with no drop in pressure. After cement set, plug was drilled and runs on R.O.P. were closed and casing pressured to 500' for 30 minutes with no appreciable drop. Drilling ahead was resumed.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Holli-Taylor Oil CorporationAddress P. O. Box 1175Farmington, New MexicoBy J. H. HowellTitle Dist. Eng.