



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office San Juan  
Lease No. 27 075-1  
Unit 1/2 Sec. 9

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 12, 1956

Well No. 5 is located 970 ft. from S line and 2005 ft. from W line of sec. 9  
SW/4 Sec. 9 (1/4 Sec. and Sec. No.) 30N (Twp.) 8E (Range) 109W (Meridian)  
Blanco (Newmont) (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 5000 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Run (132 ft) 1850' of 5 1/2" Casing 11/2. Landed at 1860'. Cemented with 100 sacks regular cement. Casing was pressured to 500' for 1 hour with no drop in pressure. After cement set, Hole was CO to 5005' w/ gas and remained dry.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Polk-Taylor Oil Corporation

Address P. O. Box 1175  
Farmington, New Mexico

By J. M. Howell  
 Title Dist. Supt.