

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

14-20-603-2172

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

NAUASO

7. UNIT AGREEMENT NAME

N.W. CHA-CHA UNIT 34

8. FARM OR LEASE NAME

✓

9. WELL NO.

146BMA

10. FIELD AND POOL, OR WILDCAT

CHA-CHA GALLUP

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

S 36-T29N-R14W

12. COUNTY OR PARISH

SAN JUAN

13. STATE

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

SLAYTON OIL CORP.

3. ADDRESS OF OPERATOR

PO Box 150, FARMINGTON, N.M.

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FSL & 660' FWL

RECEIVED

JUN 06 1985

14. PERMIT NO.

15. ELEVATIONS (SURFACE OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA)

5958 DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

THE PUMPING UNIT ON THIS WELL WAS A LUFKIN D-220, IT HAD
BROKEN DOWN twice in the last 2 years - we moved it to
32-18, which is ABOUT 1000' shallower & HAS VERY LITTLE WATER
TO LIFT. IT SHOULD DO A GOOD JOB ON THIS WELL - WE HAVE
A D 320, WHICH IS LARGER, TO PUT BACK ON 14-36. IT IS
PRESENTLY BEING ASSEMBLED. WE ARE WAITING ON A FEW
PARTS THAT HAD TO BE RE-ORDERED - WE SHOULD HAVE IT
BACK TO PUMPING IN 2-3 weeks.

18. I hereby certify that the foregoing is true and correct

SIGNED

Paul Slayton

TITLE

OPERATOR

DATE

6-4-85

(This space for Federal or State office use)

ACCEPTED FOR RECORD

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

JUN 06 1985

FARMINGTON RESOURCE AREA

BY

sm

*See Instructions on Reverse Side

NMOCC