

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

14-20-0603-10008

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Navajo Tribal

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Hogback

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Willcox

11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA

6. T29N. R16W

12. COUNTY OR PARISH 13. STATE

San Juan N. Mex.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☐ GAS WELL ☐ OTHER ☒

2. NAME OF OPERATOR

Weldon C. Julander

3. ADDRESS OF OPERATOR

Box 44, Farmington, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)

At surface

330' cel, 2310' cel

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4999 Gr.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Cement plugs set from:

Surface to 300' to cover the Gallup and Sanostee
500' to 735' (TD) cover the Dakota

270' of 4" intermediate left in hole, and 7" (31') of surface casing also left in hole. No surface marker was left as location was in cultivated field. Surface pipe and intermediate pipe was cut off about 3' below surface in accordance with USGS request.

Final surface location was cleaned up and pits filled on 3/21/67.
Surface pipe and intermediate was cut off on 3/29/67.

RECEIVED

APR 20 1967

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

18. I hereby certify that the foregoing is true and correct

SIGNED Weldon C. JulanderTITLE OperatorDATE 4-2-67

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

*See Instructions on Reverse Side