

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Dry Hole

2. NAME OF OPERATOR
Walter Duncan

3. ADDRESS OF OPERATOR
P.O. Box 234, Farmington, New Mexico 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface
990' ± 1980' ± 1
Section 12 T29N R17W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, OR, etc.)
5039 GR.

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

MAR 12 1973

MAR 13 1973

OIL CON. COM.
DIST. 3

5. LEASE DESIGNATION AND SERIAL NO.
14-20-0603-10010

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Navajo

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
North Hogback #12

9. WELL NO.
3

10. FIELD AND POOL, OR WILDCAT
Slickrock - Dakota

11. SEC. T., R., M., OR BLK. AND SURVEY OR AREA
12-29N-17W NHPM.

12. COUNTY OR PARISH
San Juan

13. STATE
New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☒

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This hole was plugged and abandoned as follows:

- 1. 15 sack cement plug was spotted from T.D. 747' to 660'.*
- 2. 12 sack cement plug was spotted from 260' to 190'.*
- 3. 8 sack cement plug was spotted from 50' to just below surface. (3')*
- 4 The 7" surface pipe was cut off below plug depth or 2' below surface and the well abandoned.*

18. I hereby certify that the foregoing is true and correct

SIGNED

James L. Jones

TITLE

Agent

DATE

3-10-73

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: