

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

NM-01772-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Aztec Oil & Gas Company	8. FARM OR LEASE NAME Reid "A"
3. ADDRESS OF OPERATOR P. O. Drawer 570, Farmington, New Mexico 87401	9. WELL NO. #2
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 940' FNL & 1530' FWL	10. FIELD AND POOL, OR WILDCAT Aztec Pictured Cliffs
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5739' GR
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 13, T29N, R10W
	12. COUNTY OR PARISH San Juan
	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

☒
☐
☐
☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

2-7-77 Pulled 1" tubing.
Set EZ drill at 2096'.
Found hole at 780'.
Squeeze cemented with 150 sacks of Class B.
Cement circulated to surface.
Pressure tested. OK.
Ran 66 jts of 1-1/2", 2.90#, J-55, 10rd tubing.
Stung into EZ drill.

10-13-77 Shut in for pressure build up.
Well has not been returned to production.
Additional remedial work may be necessary.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE District Production Mgr.

DATE October 14, 1977

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

DATE

RECEIVED

OCT 17 1977

*See Instructions on Reverse Side

S. GEOLOGICAL SURVEY