

Henry L. Burt
DEPUTY OIL & GAS INSPECTOR

DEC 1 1997

Approved

Meter Number:87087
Location Name:REID #A3
Location:TN-29 RG-10
SC-13 UL-H
2 - Federal
NMOCD Zone:OUTSIDE
Hazard Ranking Score:00

RECEIVED
APR 14 1997
OIL & GAS DIV.
EGL 3

**RATIONALE FOR RISK-BASED CLOSURE OF PRODUCTION PITS
LOCATED OUTSIDE OF THE VULNERABLE ZONE
IN THE SAN JUAN BASIN**

This production pit location was ranked according to the criteria in the New Mexico Oil Conservation Division's Unlined Surface Impoundment Closure Guidelines and received a ranking score of zero. The estimated depth to groundwater is greater than 100-feet beneath ground surface (bgs), the pit is not in a well head protection area, and there are no surface water bodies within 1,000 horizontal feet of the pit location.

The primary source, discharge to the pit has been removed. There has been no discharge to the pits for at least 4 years and the pits have been closed for at least one year.

Each pit was backfilled with clean soil and graded in a manner to divert precipitation away from the excavated area. Minimal infiltration of rainfall is expected. Any rainfall that does infiltrate the ground surface must migrate through clean backfill before reaching the residual hydrocarbons.

There is no source material at the ground surface, so direct contact of hydrocarbons with livestock and the populous is not likely.

In general, outside of the vulnerable area and alluvial valleys, bedrock material is generally encountered within 20 feet of the ground surface. Bedrock material in the San Juan Basin consists of interbedded sandstones, shales and clays. According to Freeze and Cherry, 1979, the hydraulic conductivity of the bedrock material are as follows:

Sandstone	10^{-9} to 10^{-13} cm/sec
Shale	10^{-12} to 10^{-16} cm/sec
Clay	10^{-12} to 10^{-15} cm/sec

Based on this information, the residual hydrocarbons should not migrate to groundwater.

Natural process (bioremediation) are degrading the residual hydrocarbon to carbon dioxide and water and will continue until the source is gone, therefore minimizing any impact to the environment.

Based on the above information, it is highly unlikely that any source material will impact groundwater or ever find an exposure pathway to affect human health and therefore El Paso Field Services Company (EPFS) requests closure of this pit location.

FIELD PIT SITE ASSESSMENT FORM



GENERAL

Meter: 87082 Location: Reid # A3
 Operator #: 8367 Operator Name: SOUTHLAND ROYALTY P/L District: Bloomfield
 Coordinates: Letter: H Section 13 Township: 29 Range: 10
 Or Latitude _____ Longitude _____
 Pit Type: Dehydrator _____ Location Drip: X Line Drip: _____ Other: _____
 Site Assessment Date: S.S. 94 Area: 10 Run: 73

SITE ASSESSMENT

NMOCD Zone:

(From NMOCD
Maps)

Inside

Outside

Land Type:

BLM ☒ (1)

State ☐ (2)

Fee ☐ (3)

Indian _____

Depth to Groundwater

Less Than 50 Feet (20 points) ☐ (1)

50 Ft to 99 Ft (10 points) ☐ (2)

Greater Than 100 Ft (0 points) ☒ (3)

Wellhead Protection Area :

Is it less than 1000 ft from wells, springs, or other sources of fresh water extraction? , or ; Is it less than 200 ft from a private domestic water source? ☐ (1) YES (20 points) ☒ (2) NO (0 points)

Horizontal Distance to Surface Water Body

Less Than 200 Ft (20 points) ☐ (1)

200 Ft to 1000 Ft (10 points) ☐ (2)

Greater Than 1000 Ft (0 points) ☒ (3)

Name of Surface Water Body _____

(Surface Water Body : Perennial Rivers, Major Wash, Streams, Creeks, Irrigation Canals, Ditches, Lakes, Ponds)

Distance to Nearest Ephemeral Stream ☐ (1) < 100' (Navajo Pits Only)
☐ (2) > 100'

TOTAL HAZARD RANKING SCORE: 0 POINTS

REMARKS


Remarks : ONLY PIT ON LOCATION PIT IS DRY. LOCATION IS UP ON TOP OF A MESA. REDLINE SHOWS LOCATION IS INSIDE THE V.Z. BUT TOPO SHOWS THAT IT IS OUTSIDE THE V.Z.

PUSH IN

ORIGINAL PIT LOCATION

ORIGINAL PIT LOCATION

Original Pit : a) Degrees from North 287° Footage from Wellhead 87'
b) Length : 15' Width : 15' Depth : 3'



REMARKS

Remarks :

TOOK PICTURES AT 9:45 A.M.

DUMP TRUCK-BOBTAIL

Completed By:

Robert Thompson

Signature

5.5.94

Date

FIELD IT REMEDIATION/CLOSURE FORM

GENERAL

Meter: 87087 Location: Reid A #3

Coordinates: Letter: H Section 13 Township: 29 Range: 16

Or Latitude _____ Longitude _____

Date Started : 6-8-94 Area: 10 Run: 73

FIELD OBSERVATIONS

Sample Number(s): KD 104

Sample Depth: 12 Feet

Final PID Reading 245 ppm PID Reading Depth 12 Feet

Yes No

Groundwater Encountered ☐ (1) ☒ (2) Approximate Depth _____ Feet

CLOSURE

Remediation Method :

Excavation ☐ (1) Approx. Cubic Yards 0

Onsite Bioremediation ☐ (2)

Backfill Pit Without Excavation ☒ (3)

Soil Disposition:

Envirotech ☐ (1) ☒ (3) Tierra

Other Facility ☐ (2) Name: _____

Pit Closure Date: 6-8-94 Pit Closed By: BEI

REMARKS

Remarks : Dug test Hbk thru cobbles to 12', Took PID
Sample, closed pit

Signature of Specialist: [Signature]



FIELD SERVICES LABORATORY

ANALYTICAL REPORT

PIT CLOSURE PROJECT - Soil

SAMPLE IDENTIFICATION

	Field ID	Lab ID
SAMPLE NUMBER:	100104	945402
MTR CODE SITE NAME:	87087	N/A
SAMPLE DATE TIME (Hrs):	6-8-94	1250
SAMPLED BY:	N/A	
DATE OF TPH EXT. ANAL.:	6/10/94	6/10/94
DATE OF BTEX EXT. ANAL.:	N/A	N/A
TYPE DESCRIPTION:	VG	Coarse (grey) Brown Sand

REMARKS:

RESULTS

PARAMETER	RESULT	UNITS	QUALIFIERS			
			DF	Q	M(g)	V(ml)
BENZENE		MG/KG				
TOLUENE		MG/KG				
ETHYL BENZENE		MG/KG				
TOTAL XYLENES		MG/KG				
TOTAL BTEX		MG/KG				
TPH (418.1)	1930	MG/KG			2.06	28
HEADSPACE PID	245	PPM				
PERCENT SOLIDS	92.1	%				

-- TPH is by EPA Method 418.1 and BTEX is by EPA Method 8020 --

The Surrogate Recovery was at N/A % for this sample All QA/QC was acceptable.
Narrative:

DF = Dilution Factor Used

Approved By:

[Signature]

Date:

6/16/94

Test Method for
Oil and Grease and Petroleum Hydrocarbons
in Water and Soil
Perkin-Elmer Model 1600 FT-IR
Analysis Report

74/06/10 13:11

Sample Identification
PA1402

Initial mass of sample, g
1.00

Mass of sample after extraction, g
0.99

Extraction solvent, ppm
1000

Net absorbance of extractant, 1700 cm⁻¹
0.00

