

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

NM 09717

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Tenneco Oil Company		8. FARM OR LEASE NAME Florance	
3. ADDRESS OF OPERATOR 1860 Lincoln St., Suite 1200, Denver, Colo. 80295		9. WELL NO. #37A	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1780'FSL and 1495'FEL, Unit J		10. FIELD AND POOL, OR WILDCAT Blanco Mesa Verde	
11. PERMIT NO.		12. COUNTY OR PARISH San Juan	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5952'GL		13. STATE New Mexico	
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data			

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐PULL OR ALTER CASING ☐WATER SHUT-OFF ☐REPAIRING WELL ☐FRACTURE TREAT ☐MULTIPLE COMPLETE ☐FRACTURE TREATMENT ☒ALTERING CASING ☐SHOOT OR ACIDIZE ☐ABANDON* ☐SHOOTING OR ACIDIZING ☒ABANDONMENT* ☐REPAIR WELL ☐CHANGE PLANS ☐(Other) ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

3/16/-3/21/77 - MIRUCU Perf'd 20 holes from 4807'-5101'. Broke down and sand/water frac'd formation W/ 92,200 lbs. of 20/40 mesh sand. Perf'd 20 holes from 4756'-4503'. Broke down and sand/water frac'd perfs W/ 100,000 lbs. of 20/40 mesh sand. Flowed well to clean up. Present status of well = SI for AOF test.

RECEIVED

MAR 28 1977



18. I hereby certify that the foregoing is true and correct

SIGNED

D. B. Myers

TITLE Div. Production Manager

DATE

3-23-77

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side