
Form 9-331 (May 1963)	į	JNITED STATES	SUBMIT IN TRIPLICAT	Form approved. Budget Bureau No. 42-R1424.
(May 1000)	DEPART	MENT OF THE INTI	ERIOR (Other instructions on verse side)	5. LEASE DESIGNATION AND SERIAL NO.
•	G	EOLOGICAL SURVEY	•	SF 078615
	21111001111001	6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
	SUNDRY NOTI	그 시 그 항송부탁 그 요 그 하는요 그 그		
(Do not us	e this form for propos: Use "APPLICA	그리 결혼하는 - 글 - 스타디		
1.				7. UNIT AGREEMENT NAME
	ELL XX OTHER	Northeast Blanco Unit Agrmt. No. 1, Sec. 929		
2. NAME OF OPERA	TOR	8. FARM OR LEASE NAME		
Blackwood	& Nichols Co.	Northeast Blanco Unit		
3. ADDRESS OF OPI		9. WELL NO.		
P. O. Box	1237, Durano	103A		
4. LOCATION OF WI	LL (Report location cl	go, Colorado 8130 early and in accordance with		10. FIELD AND POOL, OR WILDCAT
At surface	i below.)	Blanco Mesaverde		
176	00' F/NL & 790	11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA		
	-, -, -, -, -, -, -, -, -, -, -, -, -, -			
				Sec. 24. T30N.R8W
14. PERMIT NO.		15. ELEVATIONS (Show wheth	er DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
		6340' (GL	San Juan New Mexico
16.	Check Ap	propriate Box To Indicat	te Nature of Notice, Report, c	or Other Data
				SEQUENT REPORT OF:
	KOIRCE OF INTEN	110N 10:	SUB	
TEST WATER S	HUT-OFF P	ULL OR ALTER CASING	WATER SHUT-OFF	XX REPAIRING WELL
FRACTURE TREA	AT D	ULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACID	IZE A	BANDON*	SHOOTING OR ACIDIZING	ABANDONMENT [®] .
REPAIR WELL	c	HANGE PLANS	(Other) Surface	Casing ults of multiple completion on Well
(Other)	·		Completion or Reco	ompletion Report and Log form.)
17. DESCRIBE PROPO	SED OR COMPLETED OPER	ATIONS (Clearly state all pert	tinent details, and give pertinent da	tes, including estimated date of starting any rtical depths for all markers and zones perti-
nent to this w	vork.) *			នៃ ដីទីគេពី ដី កិត្តិសុខិ ន

- 4-1-78 Moving on location and rigging up. Spudded 12-1/4" surface hole at 5:00 P.M.
- 4-2-78 Drilled 12-1/4" hole to 271' KB; Ran 5 jts (208') 9-5/8" H-40 ST&C Rge 3 Csg and set at 222' KB, cemented with 150 sacks Class "B" with 2% CaCl and 1/4# Flocele per sack. Cement circulated, plug down @ 2:00 A.M. W.O.C. and nipple up; twelve hours test casing to 800 PSI 1/2 hour, O.K.



18. I hereby ceptify that the foregoing is true and correct		
SIGNED hitenburgo. B. Whitenburg T	TILE Drilling Supervisor	DATE 4-3-78
(This space for Federal or State office use)		
APPROVED BY	TILE	_ DATE