



STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE

GARREY CARRUTHERS
GOVERNOR

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178

September 21, 1987

Mr. Ed Alizadeh
Amoco Production Co.
2325 East 30th
Farmington, NM 87401

Re: Martinez Gas Com I #1 ³¹ K-24-24N-10W

Dear Ed:

Enclosed bradenhead test on the referenced well indicates a casing failure.

In order to comply with Rule 108, prevent waste and protect fresh water, you are hereby directed to initiate immediate remedial activity.

Yours truly,

A handwritten signature in cursive script that reads "Charles Gholson".

Charles Gholson
Deputy Oil & Gas Inspector

CG/dj

xc: Well File
Operator File



ENERGY AND MINERALS DEPARTMENT
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE

1000 RIO BRAZOS
AZTEC, NEW MEXIC
(505) 334-61

BRADENHEAD TEST REPORT
(Submit 3 copies to above address)

Date of Test 9/11/87 Operator Amoco Production Co.
Lease Name Martinez Gas Com "I" Well No. 1 Location U K Sec 24 Twp 20N Rang 10
Pressure (Shut-in or Flowing) Dwt Tubing — Intermediate — Casing 850 Bradenhead 850
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH.

TIME:	BRADENHEAD PRESSURES: INTERMEDIATE	CASING
5 Min.	<u>850</u>	<u>850</u>
10 Min.	<u>850</u>	<u>850</u>
15 Min.		
20 Min.		
25 Min.		
30 Min.		

BRADENHEAD FLOWED:	INTERMEDIATE FLOWED
Steady Flow: <u>✓</u>	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

RECEIVED
SEP 15 1987
OIL CON. DIV.
DIST. 3

If Bradenhead flowed water check description below:

Clear
Fresh
Salty
Sulfur
Black

Remarks: Bradenhead pressure would
blow down to a steady lower press
then it would pressure back up to
850 lbs. as when started. Casing never
changed.

By Denise Reter (2107)
Pumper
(Position)

Witness

CASING LEAK