DEPUTY PROPUGATION PIT CLOSURE

DEC 2 1 1998

HANLEY #2J Meter/Line ID - 89040



SITE DETAILS

Legals - Twn: 29 Rng: 10

NMOCD Hazard Ranking: 40 Operator: MERIDIAN OIL INC Sec: 18 Unit: C

Land Type: 2 - Federal Pit Closure Date: 09/09/94

RATIONALE FOR RISK-BASED CLOSURE:

The above mentioned production pit was assessed and ranked according to the criteria in the New Mexico Conservation Division's Unlined Surface Impoundment Closure Guidelines.

The primary source, discharge to the pit, has been removed. There has been no discharge to the production pit for at least five years and the pit has been closed for at least three years.

The production pit has been remediated to the practical extent of the trackhoe or to the top of bedrock. Initial laboratory analysis has indicated that the soil remaining at the bottom of the excavation is above standards based on the hazard ranking score. Contaminated soil was removed and transported to an approved landfarm for disposal. The initial excavation was backfilled with clean soil and graded in a manner to divert precipitation away from the excavated area. Any rainfall that does infiltrate the ground surface must migrate through clean backfill before reaching any residual hydrocarbons remaining in the soil. Therefore, further mobility of residual hydrocarbons is unlikely.

Since the soil samples from the initial excavation were above standards, a test boring was drilled and a sample was collected to evaluate the vertical extent of impact to soils. Test boring sample results indicated soils below standards beneath the original excavation.

El Paso Field Services Company (EPFS) requests closure of the above mentioned production pit location for the following reasons:

- Discharge to the pit has not occurred in over five years and the pit has been closed for over three years.
- The bulk of the impacted soil was removed during the initial excavation.
- The excavation was backfilled with clean soil and graded to divert precipitation away from the excavation area.
- All source material has been removed from the ground surface, eliminating potential direct contact with livestock and the general public.
- Groundwater was not encountered in the initial excavation or test boring; therefore, impact to groundwater is unlikely.
- Soil samples collected beneath the initial excavation were below standards.
- Residual hydrocarbons remaining in the soil at the bottom of the initial excavation will naturally degrade in time with minimal risk to the environment.

FIELD PIT SITE ASSESSMENT FORM

GENERAL	Meter: \$9040 Location: HANLEY # 25 Operator #: 2999 Operator Name: MERIDIANP/L District: BLOOMFIELD Coordinates: Letter: C Section /8 Township: 29 Range: 10 Or Latitude Longitude Pit Type: Dehydrator Location Drip: X Line Drip: Other: Site Assessment Date: 5:18:94 Area: 10 Run: 93								
SITE ASSESSMENT	NMOCD Zone: (From NMOCD (From NMOCD (From NMOCD (State □ (2) Maps) Inside □ (2) Indian □ Depth to Groundwater Less Than 50 Feet (20 points) □ (2) Greater Than 100 Ft (0 points) □ (3) Wellhead Protection Area: Is it less than 1000 ft from wells, springs, or other sources of fresh water extraction?, or; Is it less than 200 ft from a private domestic water source? □ (1) YES (20 points) □ (2) NO (0 points) Horizontal Distance to Surface Water Body Less Than 200 Ft (20 points) □ (2) Greater Than 1000 Ft (10 points) □ (2) Greater Than 1000 Ft (0 points) □ (2) Greater Than 1000 Ft (0 points) □ (2) Greater Than 1000 Ft (0 points) □ (2) Greater Than 1000 Ft (10 points) □ (2) Greater Than 1000 Ft (10 points) □ (2) Greater Than 1000 Ft (10 points) □ (2) One of Surface Water Body □ (1) (2) Surface Water Body: Perennial Rivers, Major Wash, Streams, Creeks, Irrigation Canals, Ditches, Lakes, Ponds) Distance to Nearest Ephemeral Stream □ (1) < 100'(Navajo Pits Only) □ (2) > 100' TOTAL HAZARD RANKING SCORE: □ POINTS								
REMARKS	REMORKS: ONLY PIT ON LOCATION. PIT IS DRY WELLHEAD IS KIND OF SEPERATED FROM THE BEST OF THE LOCATION. LOCATION IS ON THE EDGE OF THE MONTH OF POTTER CANTON NEXT TO A HOUSING SUB-DIVISION. REDUNE AND TOPO CONFIRMED LOCATION IS INSIDE V.Z. (SP3190) 04/08/94								

	ORIGINAL PIT LOCATION
ORIGINAL P. OCATION	Original Pit : a) Degrees from North Footage from Wellhead <u>\$508'</u> b) Length : Width : Depth :
	14 LOSO BELLINEAD 336°
REMARKS	Remarks: Took Pictures at 9:40 A.M. END DUMP
R	
	Completed By:
	Det Champson 5 18.94
1	Signature Date

PHASE I EXCAVATION

FIELD PIT REMEDIATION/CLOSURE FORM

GENERAL	Meter: 89040 Location: HANLEY #2J Coordinates: Letter: C Section 18 Township: 29 Range: 10 Or Latitude Longitude Date Started: 9.9.94 Run: 10 9.3
FIELD OBSERVATIONS	Sample Number(s): $\frac{12'}{}$ Feet Sample Depth: $\frac{12'}{}$ Feet Final PID Reading $\frac{006}{}$ PID Reading Depth $\frac{12'}{}$ Feet Yes No Groundwater Encountered \square \square Approximate Depth \square Feet
CLOSURE	Remediation Method: Excavation Onsite Bioremediation Backfill Pit Without Excavation Soil Disposition: Envirotech Other Facility Name: Pit Closure Date: 9-9-94 Pit Closed By: 30 Approx. Cubic Yards Tourds Tierra Pit Closed By: 30 Pit Closed By: 3
REMARKS	Remarks: Some Line markens Started Remediations to 12' 50:1 turned Light Stay. At 12' Soil Looked Clear Pid 006 Closed Pit.
	Signature of Specialist: Kelly Padella




FIELD SERVICES LABORATORY ANALYTICAL REPORT

PIT CLOSURE PROJECT - Soil Samples Inside the GWV Zone

	SAMPLE ID	ENTIFICAT	ION			
	Field ID			Lab ID	 -7	
SAMPLE NUMBER:	KP 226	946086				
MTR CODE SITE NAME:						
SAMPLE DATE TIME (Hrs):	9-9-94)/6	0.0		
SAMPLED BY:		N/A	\			
DATE OF TPH EXT. ANAL.:	9-13-91	-1		3-94		
ATE OF BTEX EXT. ANAL.:	9-14.9	L		794		
TYPE DESCRIPTION:	٧ C.		Brown.	tre)	had	
REMARKS:						
	R	ESULTS				
	RESULT	UNITS	QUALIFIERS			
PARAMETER	RESULT		DF	Q	M(g)	V(ml)
BENZENE	40.025	MG/KG	1			
TOLUENE	40.025	MG/KG				
ETHYL BENZENE	40.025	MG/KG	1			
TOTAL XYLENES	0.11	MG/KG)			
TOTAL BTEX	0.19	MG/KG				
TPH (418.1)	132.8 133	MG/KG			2.02	28
HEADSPACE PID	le	PPM	-			
PERCENT SOLIDS	92.2	%%			<u> </u>	
ne Surrogate Recovery was at	TPH is by EPA Method	418.1 and BTEX is by i % for this samp			ptable.	

Approved By: ____





ATI I.D. 409354

September 22, 1994

El Paso Natural Gas Co. P.O. Box 4990 Farmington, NM 87499

Project Name/Number: PIT CLOSURE 24324

Attention: John Lambdin

On 09/14/94, Analytical Technologies, Inc., (ADHS License No. AZ0015), received a request to analyze non-aqueous samples. The samples were analyzed with EPA methodology or equivalent methods. The results of these analyses and the quality control data, which follow each set of analyses, are enclosed.

If you have any questions or comments, please do not hesitate to contact us at (505) 344-3777.

Letitia Krakowski, Ph.D.

Project Manager

MR:jt

Enclosure



GAS CHROMATOGRAPHY RESULTS

TEST : BTEX (EPA 8020)

CLIENT : EL PASO NATURAL GAS CO. ATI I.D.: 409354

PROJECT # : 24324

PROJECT NAME : PIT CLOSURE

SAMPLE ID. #	E CLIENT I.D.	MATRIX	DATE SAMPLED	DATE EXTRACTED	DATE ANALYZED	DIL. FACTOR
10	946084	NON-AQ	09/09/94	09/14/94	09/16/94	1
11	946085	NON-AQ	09/09/94	09/14/94	09/17/94	1
12	946086	QA-NON	09/09/94	09/14/94	09/15/94	1
PARAMETER			UNITS	10	11	12
BENZENE			MG/KG		<0.025	<0.025
TOLUE			MG/KG	6.6	0.031	<0.025
_			MG/KG		<0.025	<0.025
ETHYLBENZENE TOTAL XYLENES			, MG/KG	15	<0.025	0.11
SURRO	GATE:	(%)		82	99	113

EROMOFLUOROBENZENE (%)

PHASE II

RECORD OF SUBSURFACE EXPLORATION

Philip Environmental Services Corp. 4000 Monroe Road

Farmington, New Mexico 87401 (606) 326-2262 FAX (606) 326-2388

Elevation

Borehole Location TZ9, R10, 5.18, C

GWL Depth

Logged By

Drilled By

Date/Time Started

Sixelly

Sixelly

M. Tonohul

4/9/95, 1345

Date/Time Completed

4/9/95, 1500

Borehole # BH-1
Well #
Page of

Well Logged By
Personnel On-Site
Contractors On-Site
Client Personnel On-Site

Drilling Method 4141 TD HSH Air Monitoring Method CGI, PID

Depth (Feet)	Sample Number	Sample Interval	Sample Type & Recovery (inches)	Sample Description Classification System: USCS	USCS Symbol	Depth Lithology Change (feet)	A GZ	ir Monito Jnite: NE BH	rina DU <i>5{}}</i>	Drilling Conditions & Blow Counts
10 15 20 25 30 35 35 35 35 36 36 36 36		R-0		Backfill to 12 ^l SANDY SILT, olive, 5-20% Fine Sand, dense dry TOB-ZO.0 ^l		(reet)	82	66	86	-1410

Comments:	18-20' SAMPLE (SE	K 58) sent to	lab (BTEX & TPH)
	Sample was bagged	and iced prior to	being put in jati
	of groused in	Geologist Signature	Sarah Helly

CHARRESPONTOC VIC



FIELD SERVICES LABORATORY ANALYTICAL REPORT

PIT CLOSURE PROJECT - Soil Samples Inside the GWV Zone

SAMPLE IDENTIFICATION

Field ID

SAMPLE NUMBER:	SEK 58		94719				
MTR CODE SITE NAME:	89040	Hanle	Hanley #2J				
SAMPLE DATE TIME (Hrs):	08/09/95	14:10)				
PROJECT:	Phase II D	rilling		·			
DATE OF TPH EXT. ANAL.:	3/1	1/95		95			
DATE OF BTEX EXT. ANAL.:		3/95	8/18				
TYPE DESCRIPTION:	VG		lightgrey	Sand of	clay	1	
Field Remarks:		RESULTS					
		RESULIS					
PARAMETER	RESULT	UNITS	DF	QUALIF Q			
	10.000) UF		M(g)	V(mi)	
BENZENE	20.025	MG/KG	1				
TOLUENE	40.025	MG/KG					
ETHYL BENZENE	20.025	MG/KG]				
TOTAL XYLENES	10.025	MG/KG	1				
TOTAL BTEX	20.10	MG/KG					
TPH (418.1)	48.4	MG/KG			2.09	28	
HEADSPACE PID	6	РРМ					
PERCENT SOLIDS	91.5	%					
The Surrogate Recovery was at	TPH is by EPA Method	418.1 and BTEX is by E		was accep	table.		
Narrative: AT Results	attachel						
DF = Dilution Factor Used							
Approved By:	Date:	8/20	195				

```
Test Method for
    Oil and Grease and Petroleum Hydrocarbons
               in Water and Soil
                                              孝
                                              來
          Perkin-Elmer Model 1600 FT-IR
                                              ^{*}
                Analysis Report
*************************
95/08/11 13:25
  Sample identification
947198
  Initial mass of sample, g
 2.090
  Volume of sample after extraction, ml
 29.000
*
4
 Fetroleum hydrocarbons, ppm
48.443
% Net absorbance of hydrocarbons (2930 cm-1)
0.016
*
技
         Y: Petroleum hydrocarbons spectrum
                                                           13:25
102 27
 3.T
TERES
```

3000

3290

2800

 $\odot m^{-1}$



ATI I.D. 508390

August 23, 1995

El Paso Natural Gas Co. P.O. Box 4990 Farmington, NM 87499

Project Name/Number: PIT CLOSURE/PHASE II & III 24324

Attention: John Lambdin

On 08/16/95, Analytical Technologies, Inc., (ADHS License No. AZ0015), received a request to analyze non-aqueous samples. The samples were analyzed with EPA methodology or equivalent methods. The results of these analyses and the quality control data, which follow each set of analyses, are enclosed.

If you have any questions or comments, please do not hesitate to contact us at (505) 344-3777.

Kimberly D. McNeill Project Manager

Mall

MR:jt

Enclosure

H. Mitchell Rubenstein, Ph.D. Laboratory Manager





GAS CHROMATOGRAPHY RESULTS

TEST

: BTEX (EPA 8020)

CLIENT

: EL PASO NATURAL GAS CO ATI I.D.: 508390

PROJECT #

: 24324

PROJECT NAME : PIT CLOSURE/PHASE II & III

SAMPL ID. #		MATRIX	DATE SAMPLED	DATE EXTRACTED	DATE ANALYZED	DIL. FACTOR
01	947198	NON-AQ	08/09/95	08/18/95	08/18/95	1
02	947199	NON-AQ	08/09/95	08/18/95	08/18/95	1
03	947200	NON-AQ	08/09/95	08/18/95	08/18/95	1
PARAM	ETER		UNITS	01	02	03
BENZE	NE		MG/KG	<0.025	<0.025	<0.025
TOLUE	NE		MG/KG	<0.025	0.026	<0.025
ETHYL	BENZENE		MG/KG	<0.025	<0.025	<0.025
TOTAL	XYLENES		MG/KG	<0.025	0.057	0.058
SURRO	GATE:					
BROMO	FLUOROBENZENE	(%)		88	88	93