**9-331** 1973

-

1100000

Form Approved. Budget Bureau No. 42-R1424

5. LEASE

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

DEPARTMENT OF THE INTERIOR	SF-0/8109
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	Gallegos Canyon Unit  8. FARM OR LEASE NAME
	6. FARM OR LEASE NAME
1. oil gas Well other	9. WELL NO. 13 4 3 4 5 4 7
2. NAME OF OPERATOR	285
Energy Reserves Group, Inc.	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	West Kutz - Pictured Cliffs
P. O. Box 3280 Casper, Wyoming 82602	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA 설치를 및 실관계를
below.)	Sec. 31-T29N-R12W
AT SURFACE: 980' FSL & 920' FWL (SW SW) AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE
AT TOTAL DEPTH:	San Juan New Mexico  14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO. \$448 9 3884
REPORT, OR OTHER DATA	15 FLEVATIONS (SHOW DE KDR AND WD)
	15. ELEVATIONS (SHOW DF, KDB, AND WD) G.L. 5,522'; K.B. 5,532'
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	the state of the s
TEST WATER SHUT-OFF	-2 $-2$ $-2$ $-2$ $-2$ $-2$ $-2$ $-2$
FRACTURE TREAT	사용하다 그 사용하다
REPAIR WELL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING	change on Form 9–330.)
MULTIPLE COMPLETE	
ABANDON*	그 그는 사람이 가을 하는 것이 되었다. 그 경기 없는 것이 없다고 있다.
(other) Well History X	
17 DESCRIPT PROPOSED OF COMPLETED OPERATIONS (Clearly state	a all postingst details, and give postingst datas
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and	
measured and true vertical depths for all markers and zones pertiner	nt to this work.)*
	도 보고 있는 사람들이 되었다. 그 사람들은 보고 있는 것이 되었다. 
$\sim$ The above described well was spudded at $1$	
Drilled 12½" hole to 130'. Ran 3 jts 8 5/8" O.D., 36#, J-55, R-3, SS, ST&C,	
8Rth New Casing set @ 126' (K.B.). Cemented w/100 sx of Class "B" cement w/2%	
CaCl <sub>2</sub> . Plug down @ 11:00 a.m., 9-9-79. Good cement returns.  Nippled up and pressure tested BOPE to 600 PSI, held O.K.	
Drilled 6 3/4" hole to 1,550' (K.B.) and ran logs.	
Ran 38 jts $4\frac{1}{2}$ " O.D., $10.79\%$ , BE, 8Rth, SS	
Cemented w/100 sx of 65-35 pozmix w/12% gel &	
Class 'B' cmenet w/1%' Flocele/sx. Plug down	
9-14-79 - W.O.C. & W.O.C.T.	
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct	
1/0/9:10	224191
SIGNED TITLE Drig. Supt SE	P 2 4 COM 9- 8-79
18. I hereby certify that the foregoing is true and correct  SIGNED  TITLE Dr1g. Supt GEP 2 page 1979  (This space for Federal or State of Fice Use) - 3	
APPROVED BYTITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:	
	그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그