

|                       |  |
|-----------------------|--|
| N. OF COPIES RECEIVED |  |
| DISTRIBUTION          |  |
| SANTA FE              |  |
| FILE                  |  |
| U.S.G.S.              |  |
| LAND OFFICE           |  |
| OPERATOR              |  |

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State  Fee

5. State Oil & Gas Lease No.

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

|  |   |
|--|---|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> <b>P &amp; A</b>  | 7. Unit Agreement Name  |
| 2. Name of Operator<br><b>Harlan Drilling Company</b>  | 8. Farm or Lease Name<br><b>Hartman</b>                         |
| 3. Address of Operator<br><b>Post Office Box 1367, Farmington, NM 87401</b>  | 9. Well No.<br><b>1-Y</b>                                       |
| 4. Location of Well<br>UNIT LETTER <b>K</b> <b>1450</b> FEET FROM THE <b>West</b> LINE AND <b>1580</b> FEET FROM<br>THE <b>North</b> LINE, SECTION <b>31</b> TOWNSHIP <b>29N</b> RANGE <b>11W</b> N.M.P.M. | 10. Field and Pool, or Wildcat<br><b>Fulcher - Kutz P/C</b> Ext |
| 15. Elevation (Show whether DF, RT, GR, etc.)<br><b>5376' GL</b>   | 11. County<br><b>San Juan</b>                                   |

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK

TEMPORARILY ABANDON

PULL OR ALTER CASING

OTHER

PLUG AND ABANDON

CHANGE PLANS

SUBSEQUENT REPORT OF:

REMEDIAL WORK

COMMENCE DRILLING OPNS.

CASING TEST AND CEMENT JOB


OTHER

ALTERING CASING

PLUG AND ABANDONMENT

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-18-79 - Plug and abandon - Total Depth Reached 315' - Cement Block to Surface (Plug) - 35 Sacks B Cement.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Pete Staley TITLE Production Manager DATE 1-21-81

Original Signed by FRANK T. CHAVEZ

APPROVED BY \_\_\_\_\_ TITLE SUPERVISOR DISTRICT #3 DATE JAN 22 1981

CONDITIONS OF APPROVAL, IF ANY: