1-6-81

UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

FARMINGTON DISTRICT

Form 9-331 Dec. 1973	Form Approved. Budget Bureau No. 42–R1424
UNITED STATES DEPARTMENT OF THE INTERIOR	5. LEASE SF 077092
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas well other	Lackey A 9. WELL NO.
2. NAME OF OPERATOR	IR (PM)
El Paso Natural Gas Company	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR P.(). Box 289, Farmington, NM	Aztec PC & Blanco MV 11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	AREA Sec.12, T-29-N, R-10-W
AT SURFACE: 830'N, 830'E	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	San Juan New Mexico
16. CHECK AFPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO.
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 5663' GL
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	777 AND
TEST WATER SHUT-OFF [The second secon
FRACTURE TREAT	
REPAIR WELL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING	change on Form 9-330.)
MULTIPLE COMPLETE	•
ABANDON*	N. C.
(other)	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is a measured and true vertical depths for all markers and zones pertine	directionally drilled, give subsurface locations and
: Spudded well. Drilled surface hole. surface casing 219' set at 233'. Ce to surface. WOC 12 hour; held 600#/	emented w/224 cu. ft. cement.Ci
81: TD 2513'. Ran 58 joints of 7", 20# 2502' set at 2513'. Cemented w/483	
hours; held 1200#/30 minutes. Top o	
81: TD 4906'. Ran 63 joints of 4 1/2", 2536'. set 370-4906'. Float collar 452 cu. ft. cement. WOC 18 hours.	
Subsurface Safety Valve: Manu. and Type	Set @ Ft.

rc

El Paso Natural Gas Company	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Aztec PC & Blanco MV
P.(). Box 289, Farmington, NM	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA Sec.12, T-29-N, R-10-W
below.)	NMPM
AT SURFACE: 830'N, 830'E	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	San Juan New Mexico
	14. API NO.
16. CHECK AFPROPRIATE BOX TO INDICATE NATURE OF NOTICE	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	5663' GL
TEST WATER SHUT-OFF X	The state of the s
FRACTURE TREAT	
SHOOT OR ACIDIZE	
REPAIR WELL	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
PULL OR ALTER CASING	Change on Form 5-330.)
CHANGE ZONI:S	*
ABANDON*	, · · · · · · · · · · · · · · · · · · ·
(other)	
surface casing 219' set at 233'. C to surface. WOC 12 hour; held 600# 1-10-81: TD 2513'. Ran 58 joints of 7", 20# 2502' set at 2513'. Cemented w/48: hours; held 1200#/30 minutes. Top 6 1-13-81: TD 4906'. Ran 63 joints of 4 1/2", 2536'. set 370-4906'. Float collar 452 cu. ft. cement. WOC 18 hours.	/30 minutes. #, K-55 intermediate casing 3 cu. ft. cement. WOC 12 of cement at 400'. 10.5#, K-55 casing liner
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby cartify that the foregoing is true and correct	
	Clark 17 1001
SIGNED W. J. J. J. TITLE DETTING	Clerk DATE January 13, 1981
(This space for Federal or State	office use)
APPROVED BY TITLE	DATE
CONDITIONS O A DOCENTED FOR HESUMU	
JAN 21 1981 NMOO	•
*See Instructions on Revers	se Side