## UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

m 9–331 cc. 1973	Form Approved. Budget Bureau No. 42–R1424		
UNITED STATES DEPARTMENT OF THE INTERIOR	5. LEASE SF-076958		
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
SUNDRY NOTICES AND REPORTS ON WELLS not use this form for proposals to drill or to deepen or plug back to a different	7. UNIT AGREEMENT NAME		
ervoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME		
oil gas X other	Hare		
well well other  NAME OF OPERATOR	9. WELL NO. 19-E		
Southland Royalty Company ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME Basin Dakota		
P. O. Drawer 570, Farmington, New Mexico LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 1050' FNL & 1650' FWL AT TOP PROD. INTERVAL:	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 23-T29N-R10W		
	12. COUNTY OR PARISH 13. STATE San Juan New Mexico		
AT TOTAL DEPTH:	14. API NO.		
CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	<u> </u>		
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 5746' GR		
QUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:  ST WATER SHUT-OFF   ACTURE TREAT   OOT OR ACIDIZE   PAIR WELL   LL OR ALTER CASING   ILTIPLE COMPLETE   ANGE ZONES   ANDON*  SPUIN AND CORING POPORT	(NOTE: Report results of multiple completion or zone change on Form 9–330.)		

APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE	DATE		
(This s	pace for Federal or State office us	se)		
SIGNED TI	TLE Dist. Prod. Mgr	November	5, 1979	
18. I hereby certify that the foregoing is true and				
Subsurface Safety Valve: Manu. and Type		Set	@ Ft	
235'. 11-03-79 Ran five joints (2 Cemented with 200	urface hole at 11:19 216.43') of 9-5/8", sacks of Class "B" ug down at 10:00 A.M	32#, K-55 casi , 1/4# cellofla	ng set at 229'. ke per sack	
17. DESCRIBE PROPOSED OR COMPLETED OF including estimated date of starting any promeasured and true vertical depths for all managements.	oposed work. If well is direct arkers and zones pertinent to	ionally drilled, give subthis work.)*	osurface locations and	
CHANGE ZONES  ABANDON*  (other) Spud and Casing Report				
TEST WATER SHUT-OFF		NOTE: Report results of m change on Form 9-	, ,	
16. CHECK APPROPRIATE BOX TO INDICATE REPORT, OR OTHER DATA  REQUEST FOR APPROVAL TO: SUBSEQ		ELEVATIONS (SHOW 5746 GR	/ DF, KDB, AND WD)	
below.) AT SURFACE: 1050' FNL & 1650' AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	14	Section 23-12. COUNTY OR PARISH San Juan API NO.		
P. O. Drawer 570, Farmington, 4. LOCATION OF WELL (REPORT LOCATION OF	O. Drawer 570, Farmington, New Mexico CATION OF WELL (REPORT LOCATION CLEARLY. See space 17  AREA  Scattism 22.7		R BLK, AND SURVEY OR	
Southland Royalty Company 3. ADDRESS OF OPERATOR	10	10. FIELD OR WILDCAT NAME Basin Dakota		
well well other  2. NAME OF OPERATOR	S	. WELL NO. 19-E		
(Do not use this form for proposals to drill or to deepen reservoir. Use Form 9–331–C for such proposals.)  1. oil gas the proposals of the proposals.		. FARM OR LEASE NAI Hare	ME	