REPAIR WELL

PULL OR ALTER CASING

MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other)

(NOTE: Report results of multiple completion or zone

190 4

change on Form 9-330.)

LINITED STATES

DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	5. LEASE NM 03877 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME
1. oil gas X other	Duff 9. WELL NO.
2. NAME OF OPERATOR El Paso Natural Gas Company 3. ADDRESS OF OPERATOR	7 10. FIELD OR WILDCAT NAME Bloomfield Chacra Ext.
Box 289, Farmington, New Mexico 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 8, T-29-N, R-11-W
AT SURFACE: 905'S, 740'E AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	12. COUNTY OR PARISH San Juan New Mexico
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND ND)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF	5672' GL

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

10-24-79: Spudded well. Drilled surface hole. Ran 3 joints 8 5/8", 24#, KS surface casing 119' set at 131'. Cemented w/ 89 cu. ft. cement. Circulated to surface WOC 12 hours; held 600#/30 minutes.

001 20 1979 U. S. GEOLOGICAL SURVEY GORGERON, N. M.

Subsurface Safety Valve: Manu. and Type Set @ 18. I hereby gertify that the foregoing is true and correct Drilling Clerk October 25 SIGNED (This space for Federal or State office use)

APPROVED BY CONDITIONS OF APPROVAL, IF ANY: _ TITLE _

DATE

NMOCC