

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well gas ☒ well other ☐
2. NAME OF OPERATOR  
Southland Royalty Company
3. ADDRESS OF OPERATOR  
P.O. Drawer 570, Farmington, New Mexico
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 1120' FNL & 1070' FWL  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

- | REQUEST FOR APPROVAL TO:       |                                     | SUBSEQUENT REPORT OF: |                                     |
|--------------------------------|-------------------------------------|-----------------------|-------------------------------------|
| TEST WATER SHUT-OFF            | <input type="checkbox"/>            |                       | <input type="checkbox"/>            |
| FRACTURE TREAT                 | <input type="checkbox"/>            |                       | <input type="checkbox"/>            |
| SHOOT OR ACIDIZE               | <input type="checkbox"/>            |                       | <input type="checkbox"/>            |
| REPAIR WELL                    | <input type="checkbox"/>            |                       | <input type="checkbox"/>            |
| PULL OR ALTER CASING           | <input type="checkbox"/>            |                       | <input type="checkbox"/>            |
| MULTIPLE COMPLETE              | <input type="checkbox"/>            |                       | <input type="checkbox"/>            |
| CHANGE ZONES                   | <input type="checkbox"/>            |                       | <input type="checkbox"/>            |
| ABANDON*                       | <input type="checkbox"/>            |                       | <input type="checkbox"/>            |
| (other) Spud and Casing Report | <input checked="" type="checkbox"/> |                       | <input checked="" type="checkbox"/> |

5. LEASE  
SF-077317
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME  
Cooper
9. WELL NO.  
4-E
10. FIELD OR WILDCAT NAME  
Basin Dakota
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Section 18, T29N, R11W
12. COUNTY OR PARISH  
San Juan
13. STATE  
New Mexico
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)  
5629' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

2/18/81 Spudded 12-1/4" surface hole and drilled to 96'.

2/19/81 Drilled 12-1/4" hole to 250'. Ran 5 joints (223.01') of 8-5/8", 24#, K-55 casing set at 235'. Cemented with 250 sacks of Class "B" with 1/4# flocele per sack and 3% CaCl<sub>2</sub>. Plug down at 1:30 P.M. 2-19-81. Cement circulated to surface.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_

18. I hereby certify that the foregoing is true and correct

SIGNED *Arthur J. [Signature]* TITLE Drilling Clerk DATE February 20, 1981

(This space for Federal or State office use)

APPROVED BY FEB 24 1981 TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

BY *AW* FARMINGTON DISTRICT

NMOCC