DEPUTY OIL & GAS INSPECTOR

DEC 3 0 1997

Meter Number: 93781

Location Name: JOHNSON GAS COM C #1E

Location:TN-29 RG-12 SC-07 UL-L

4 - Fee

NMOCD Zone:OUTSIDE Hazard Ranking Score:00



RATIONALE FOR RISK-BASED CLOSURE OF PRODUCTION PITS LOCATED OUTSIDE OF THE VULNERABLE ZONE IN THE SAN JUAN BASIN

This production pit location was ranked according to the criteria in the New Mexico Oil Conservation Division's Unlined Surface Impoundment Closure Guidelines and received a ranking score of zero. The estimated depth to groundwater is greater than 100-feet beneath ground surface (bgs), the pit is not in a well head protection area, and there are no surface water bodies within 1,000 horizontal feet of the pit location.

The primary source, discharge to the pit has been removed. There has been no discharge to the pits for at least 4 years and the pits have been closed for at least one year.

Each pit was backfilled with clean soil and graded in a manner to divert precipitation away from the excavated area. Minimal infiltration of rainfall is expected. Any rainfall that does infiltrate the ground surface must migrate through clean backfill before reaching the residual hydrocarbons.

There is no source material at the ground surface, so direct contact of hydrocarbons with livestock and the populous is not likely.

In general, outside of the vulnerable area and alluvial valleys, bedrock material is generally encountered within 20 feet of the ground surface. Bedrock material in the San Juan Basin consists of interbedded sandstones, shales and clays. According to Freeze and Cherry, 1979, the hydraulic conductivity of the bedrock material are as follows:

 10^{-9} to 10^{-13} cm/sec 10^{-12} to 10^{-16} cm/sec 10^{-12} to 10^{-15} cm/sec Sandstone Shale Clay

Based on this information, the residual hydrocarbons should not migrate to groundwater.

Natural process (bioremediation) are degrading the residual hydrocarbon to carbon dioxide and water and will continue until the source is gone, therefore minimizing any impact to the environment.

Based on the above information, it is highly unlikely that any source material will impact groundwater or ever find an exposure pathway to affect human health and therefore El Paso Field Services Company (EPFS) requests closure of this pit location.

FIELD PIT SITE ASSESSMENT FORM LEUFLE

GENERAL	Meter: 93781 Location:						
SITE ASSESSMENT	NMOCD Zone: Inside Land Type: BLM ☐ (From NMOCD Vulnerable State ☐ Maps) Zone ☐ Fee ☒ Outside ☒ Indian ☐ Depth to Groundwater Less Than 50 Feet (20 points) ☐ 50 Ft to 99 Ft (10 points) ☐ Greater Than 100 Ft (0 points) ☒ Wellhead Protection Area: Is it less than 1000 ft from wells, springs, or other sources of fresh water extraction?, or; Is it less than 200 ft from a private domestic water source? ☐ YES (20 points) ☒ NO (0 points) Horizontal Distance to Surface Water Body Less Than 200 Ft (20 points) ☐ 200 Ft to 1000 Ft (10 points) ☐ Greater Than 1000 Ft (0 points) ☐ Greater Than 1000 Ft (0 points) ☒ Name of Surface Water Body ☐ (Surface Water Body: Perennial Rivers, Major Wash, Streams, Creeks, Irrigation Canals, Ditches, Lakes, Ponds) TOTAL HAZARD RANKING SCORE: Points						
REMARKS	Remarks: THREE PITS ON LOCATION. WILL CLOSE ONLY ONE. LOCATION IS FENCED OFF. PIT IS DRY.						

	ORIGINAL PIT LOCATION
NO	Original Pit: a) Degrees from North Footage to Wellhead b) Degrees from North Footage to Dogleg Dogleg Name c) Length: Width: Depth:
ORIGINAL PIT LOCATION	IN SELIMEND
REMARKS	Remarks: STARTED THRING PICTURES AT 9:09 A.M. END DUMP
	Completed By: Signature 3.23.94 Date

FIEL PIT REMEDIATION/CLOSU 3 FORM

GENERAL	Meter: 93781 Location: Johnson Gras Com C+1E Coordinates: Letter: L Section 7 Township: 29 Range: 12 Or Latitude Longitude Date Started: 5-11-94 Area: 02 Run: 22
FIELD OBSERVATIONS	Sample Number(s): 12^{\prime} Feet Sample Depth: 12^{\prime} Feet Final PID Reading $2/3$ PID Reading Depth 12^{\prime} Feet Yes No Groundwater Encountered \square (1) \square (2) Approximate Depth \square Feet
CLOSURE	Remediation Method : Excavation
	Soil Disposition: Envirotech (1) (3) Tierra Other Facility (2) Name: Pit Closure Date: 5-11-94 Pit Closed By: \$\frac{\beta \in \cdot 1}{\beta \in \cdot 1}\$
REMARKS	Remarks: FPNG I've Millers . Soil changed color at 11."
R	Signature of Specialist: Vale Wison



FIELD SERVICES LABORATORY ANALYTICAL REPORT PIT CLOSURE PROJECT - Soil

SAMPLE IDENTIFICATION

_	SAMPLE NUMBER: Vi w 55 MTR CODE : SITE NAME: 93781		·	Lab ID		
SAMPLE NUMBER:			945130			
MTR CODE : SITE NAME:			!	N/A		
SAMPLE DATE : TIME (Hrs): SAMPLED BY:		5-11-91		0750		
		N/A				
DATE OF TPH EXT. ANAL.:	TEX EXT. ANAL.:					
ATE OF BTEX EXT. ANAL.			A NIA			
TYPE : DESCRIPTION:			Gray Sand			
REMARKS:						
		RESULTS				
		HAUTC		QUALIFIERS		
PARAMETER	RESULT	UNITS	DF	Q	M(g)	V(mi
BENZENE		MG/KG				
TOLUENE		MG/KG				
ETHYL BENZENE		MG/KG				
TOTAL XYLENES		MG/KG				
TOTAL BTEX		MG/KG				
TPH (418.1) 19,400	1937 Chil	MG/KG			155	28
HEADSPACE PID	213	PPM				
PERCENT SOLIDS	92.1	%				
	- TPH is by EPA Method			was acce	atable	

