

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator Southland Royalty Company	8. Farm or Lease Name Manqum "B" Com
3. Address of Operator P.O. Drawer 570, Farmington, New Mexico 87401	9. Well No. 1-E
4. Location of Well UNIT LETTER <u>M</u> , <u>1020</u> FEET FROM THE <u>South</u> LINE AND <u>1045</u> FEET FROM THE <u>West</u> LINE, SECTION <u>32</u> TOWNSHIP <u>29 North</u> RANGE <u>11 West</u> NMPM.	10. Field and Pool, or Wildcat Basin Dakota
15. Elevation (Show whether DF, RT, GR, etc.) 5478' GR	12. County San Juan

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <u>Spud & Casing Report</u> <input checked="" type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-07-81 Spudded 12-1/4" surface hole at 7:30 P.M. 11-7-81 and drilled to a total depth of 245'. Ran 5 joints (229') of 8-5/8", 24#, K-55 casing set at 240'. Cemented with 225 sacks of Class "B" with 1/4# flocele per sack and 3% CaCl₂. Plug down at 12:15 A.M. 11-8-81. Cement circulated.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Ruth H. Chavez</u>	TITLE <u>Drilling Clerk</u>	DATE <u>November 09, 1981</u>
APPROVED BY <u>Original Signed by FRANK T. CHAVEZ</u>	TITLE <u>SUPERVISOR DISTRICT # 3</u>	DATE <u>NOV 12 1981</u>
CONDITIONS OF APPROVAL, IF ANY:		