Form 9-331 Dec. 1973

4.4(14)

## UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

_	Form Approved. Budget Bureau No. 42-R1424					
	5. LEASE					
-	SF-077056					
_	6. IF INDIAN, ALLOTTEE OR TRIBE NAME					
t	7. UNIT AGREEMENT NAME					
_	8. FARM OR LEASE NAME					
-	Cozzens					
-	9. WELL NO.					
-	6-E  10. FIELD OR WILDCAT NAME					
-						
ŀ	Basin Dakota/Undesignated Gallu 11. SEC., T., R., M., OR BLK. AND SURVEY OF					
-	AREA					
	Section 18, T29N, R11W					
١	12. COUNTY OR PARISH 13. STATE					
].	San Juan New Mexico					
-	14. API NO.					
-	15. ELEVATIONS (SHOW DF, KDB, AND WD)					
	5613' GR 1					
-						
, _						
	(NOTE: Report results of multiple completion or zone					
	change on form 9-330.)					
<u>``</u>	73X, X. im					
	The state of the s					
te	all pertinent details, and give pertinent dates,					
air	ectionally drilled, give subsurface locations and to this work.)*					
	to this work.)					
	011 4 50 11 5 5 5					
5/8	8", 4.70#, J-55, EUE tubing.					
	", 4.70#, J-55, EUE tubing					
O	, 4.70", 3-33, EUE tubing					
	Set @ Ft.					
	Tt.					
in	August 10 1001					
111	neer DATE August 18, 1981					
fice	use)					
	DATE					

		EPORTS ON WELLS		GREEMENT NAME	
(Do not use this for reservoir, Use Form	rm for proposals to drill or t 9–331–C for such proposals	to deepen or plug back to a different (.)	9 EADM C	ND LEAST MANE	
1. oil	gas 🕥	-  _	8. FARM OR LEASE NAME Cozzens		
well 🗀	well other		9. WELL NO.		
2. NAME OF C	PERATOR	6-E			
	Royalty Company	10. FIELD C	10. FIELD OR WILDCAT NAME		
3. ADDRESS O		Basin Dal	Basin Dakota/Undesignated Gallup		
P.O. Draw	er 570, Farmingt	11. SEC., T.	11. SEC., T., R., M., OR BLK. AND SURVEY OR		
4. LOCATION ( below.)	OF WELL (REPORT LOCA	AREA	AREA Section 18, T29N, R11W		
AT SURFACE: 1540' FSL & 1655' FEL AT TOP PROD. INTERVAL:			12. COUNTY OR PARISH 13. STATE		
AT TOTAL DEPTH:			San Juan New Mexico		
16 CHECK ADD	ROPRIATE BOX TO IN	_ 14. API NO.			
REPORT, OF	ROPRIATE BOX TO IN		IONS (SHOW DF, KDB, AND WD)		
REQUEST FOR A	APPROVAL TO:	SUBSEQUENT REPORT OF	<del>- 5613' (</del>	iR _	
TEST WATER SH	IUT-OFF	D REC			
FRACTURE TREA		n mark	. And the second		
SHOOT OR ACID REPAIR WELL	)/ZE	L AUA.	A BANGANAN Language Angles		
PULL OR ALTER	CASING		(NOTE: Repo	ort results of multiple completion or zone ige on form 9–330.)	
MULTIPLE COMP	PLETE		30a Al Go <b>ave</b> 2738, S. III	ge 017 g01111 9=350.)	
CHANGE ZONES			G1777, 17. 16.		
ABANDON* (other)					
(other)					
		any proposed work. If well is c r all markers and zones pertine		details, and give pertinent dates, lled, give subsurface locations and *	
7-24-81	Pulled 210 join	nts (6429.85') of 2-3	/8", 4.70#	, J-55, EUE tubing.	
8-07-81	Relanded 209 jo at 6409'.	oints (6397') of 2-3/	8", 4.70#,	J-55, EUE tubing	
Subsurface Safety	y Valve: Manu. and Type			Set @ Ft.	
18. I hereby certi	fy that the foregoing is ti	rue and correct			
		TITLE District Eng	ineer DATE	August 18, 1981	
		(This space for Federal or State off	ice use)	all the second second	
APPROVED BY		TITLE			
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:			DATE	16 2 ± 198°	
				ALCO N - 100	
				MULMINGTON OF THE	
		*See Instructions on Reverse S	BY		